

ecology and environment, inc.

Site: Lourd History.
ID F: 180980353297
Break: 167
Other.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Pete Culver, RPO

THRU:

Philip Dula, Assistant Manager

FROM:

E & E/FIT

DATE:

December 8, 1989

SUBJECT:

Data Summary for the Screening Site Inspection of the Linwood Mining and Minerals Site (formerly Umthun Trucking), Buffalo,

Iowa.

TDD# F-07-8809-008

PAN# FIAO236SA

Site# V86

Project# 001

Superfund Contact: Pete Culver Fit Project Leader: Wesley McCall 30815356 Superfund

INTRODUCTION

The Ecology and Environment, Inc., Field Investigation Team (E & E/FIT) was tasked by the Region VII U.S. Environmental Protection Agency (EPA) to conduct a Screening Site Inspection (SSI) of the Linwood Mining and Minerals Site (formerly Umthun Trucking). The site is located in Buffalo, Iowa, approximately five miles southeast of Davenport (Figure 1).

The purpose of this SSI was to determine whether ground water or surface water is being contaminated by heavy metals from fly ash deposited on site. Fly ash from coal-fired lime kilns has been dumped on the ground surface over approximately three acres, and has been vented/precipitated into several acres of the abandoned underground mine works. The FIT collected ground water samples from existing wells, and surface water, sediment, soil, and fly ash to characterize site conditions.

SITE BACKGROUND

Umthun Trucking installed a private well in 1983 at their Buffalo terminal. Complaints by employees at the terminal concerning the well water were initially investigated by the County health department and later by State officials. Samples collected from the Umthun well at this time displayed elevated concentrations of some heavy metals and a low pH. Further work by State and local officals revealed that the Umthun well was cased through the abandoned mine works of the Linwood Quarry which was used for venting flue gases and particulates from the lime kilns. The well was re-cased and grouted and no further problems have occurred.

The Linwood Quarry began operation as an open limestone pit mine. The site was purchased by the McCarthy Improvement Company in 1940 and

in 1956 began subsurface mining as removal of the overburden became uneconomical. Initially, subsurface mining was done in the Devonian-age Davenport Formation. The underground works on the upper level have a 25-foot ceiling with 30-foot diameter pillars on 70-foot centers. Approximately 500 acres have been mined on this level. The Scott County landfill occupies approximately 100 acres overlying the northern portion of the underground works.

More recently, quarrying has begun on a second, lower level in the mine. Limestone is being taken from the Otis Formation, also of Devonian Age. Approximately 60 acres have been mined from the Otis Formation.

Three coal-fired lime kilns are maintained and operated on site by Linwood Quarry. The kilns are situated on the south side of Highway 22 near the office building (Figure 2). Until 1974 the kiln fly ash was vented to the atmosphere. At that time 160 acres of the upper level in the mine was walled off and a seven-foot diameter duct was emplaced from the kilns to this inactive area. Precipitating units at the kilns remove the >5 micron diameter particulates from the kiln fly ash. The finer particulate fly ash is routed to the sealed-off underground works via the ductwork and blowers. The fly ash vents into the large mine cavity underground where the fly ash is precipitated on the floors and wall of the cavity. Buildup pressure in the cavity is released to the atmosphere through a nine-foot diameter vent located approximately 2,000 feet northwest of the Umthun terminal.

Gaillard Krewer, Director of Mine Operations, informed the FIT that effluent from the vent is occasionally monitored for opacity by state regulators. Krewer also indicated that the State of Iowa was setting up a sulfur dioxide monitoring station northeast of the vent at the corner of the Wilson Trucking property.

A review of the cultural, climatic, and geologic conditions at this site was presented in the Work Plan for this project (E & E 1989). Refer to this report for further information and detail.

FIELD ACTIVITIES

Field activities were conducted the week of May 22, 1989, by FIT members Wes McCall, team leader; Gayle Hubert, site safety officer; and Rob Parsons and Debbie Fischer, environmental technicians. Site access was granted by Gaillard Krewer.

Soil, Ash, and Sediment Sampling

Fly ash samples were collected to determine the concentration of heavy metals present on site. Soil and sediment samples were collected to characterize background conditions and determine if any local contamination of these matrices has occurred. Each sample consisted of five aliquots taken from 0 to 6 inches with stainless steel spoons and homogenized in aluminum tins.

Table 1 summarizes the samples collected, and sample locations are depicted on Figure 2. The sample series for this activity was DC943.

Four samples and a duplicate (031 through 034D) were collected from the ash piles northeast of the Umthun Trucking terminal. According to Krewer, this ash was emplaced from 1975 to 1976. Samples were collected of the ash currently being produced at the bag house and blowers (040 and 041) at the lime plant. These two samples were collected from kiln ash that was spilled on the ground.

Sediment samples were collected from Moore and Donaldson creeks which transect the site in a general north-south trend and empty into the Mississippi River. Samples were collected from Moore Creek upstream of the ash piles (036) and from just below these piles (038). Donaldson Creek crosses the Scott County Landfill before flowing past the Linwood Quarry. Samples were collected from three locations on Donaldson Creek: north of the landfill (043); between the landfill and the quarry (039); and below the quarry near the confluence of the creek and the Mississippi River (042). Sediments were collected after corresponding surface water sampling was completed. A downgradient soil sample was taken at the Umthun Trucking terminal (037) about 50 feet north of the well head. Two background soil samples were collected: one at the Moses residence (044); and one from just north of the surface kiln ash (035).

Water Sampling

Twenty water samples were collected. Ground water samples were collected from industrial, municipal, and residential wells; surface water samples were collected from corresponding sediment sample locations; and samples of mine water were collected from Linwood Mining operations. The surface water samples were collected at the same locations as sediment samples, before sediments were disturbed. Wells were purged for three to five minutes before samples were collected. Sample locations are summarized in Table 2 and sample locations are illustrated on Figures 1 and 2.

In an effort to characterize the mine effluents, three mine water samples, plus one duplicate, were collected. Sample 016 was collected from the discharge pond which occupies the bottom of the abandoned quarry pit, and is used to rinse the stone and reduce dust at the mine. Mine waters seeping and flowing in the mine were collected at the lower level in the mine at one location and pumped to a surface holding pond. The collection point is 186 feet below the surface. Sample 017 and its duplicate, 017D, were collected from the six-inch conduit at the surface pond. A third sample of the mine water was collected from the floor of the second level of the mine. This sample (015) was taken below a portion of the abandoned mine works that was sealed off to receive kiln effluents and ash particulates. The roof and walls displayed little evidence of seepage.

Ten wells were sampled during this SSI. Alvin Lee, Assistant Manager of the Linwood Limeplant, escorted the field crew to the wells at the Linwood office (014), quarry bathhouse (013), and lime plant (012). The Umthun Trucking well (003) was resampled. This well had elevated concentrations of heavy metals and low pH (2.7) when previously sampled by the Iowa Department of Natural Resources (IDNR). The well has been re-cased and grouted since the IDNR sampling.

The supply well for the Scott County landfill (005), which overlies a portion of the mine, was sampled. The well is 325 feet deep and has a static water level of 170 feet. Buffalo City well #2 was in operation and a sample (019) was collected. The sample was chlorinated, as there was no access valve before the chlorination system. The total depth of the well is 405 feet, with the pump at 145 feet. According to Ralph Jewett, Water Commissioner, the water quality from well #2 has deteriorated within the past year. The water contained a high concentration of dissolved solids and had a sulfur odor.

Samples from wells at the (b) (9) (008) and (b) (9) (018) residences were collected to serve as background. Samples were also collected from two residential wells adjacent to the site: (b) (9) (009) and (b) (9) (010). The (b) (9) complained of poor water quality, including hardness and sulfur odor.

ANALYTICAL RESULTS

Surface Water

One sample on Moore Creek was collected upgradient of the ash piles (001) and a second sample (004) was collected downgradient of the ash piles. The upgradient sample was found to contain 12 μ g/l chromium while both samples had 50 μ g/l or less barium. Samples 006, 007, and 011, which were collected from Donaldson Creek, display increasing levels of chromium; concentrations were below the detection limit at the background location and increased to 28 μ g/l at the confluence with the Mississippi River. All of these concentrations are well below the MCLs established by the EPA (Table 3).

The anion tests for chloride and sulfate did not reveal a distinct trend of increasing levels from upgradient to downgradient samples. Chloride concentrations did not exceed 100 mg/l in any of the stream samples, while sulfate levels were above 250 mg/l in most of these samples (Table 3). None of the stream water sampled is used for potable water.

Ground Vater

Three of the ten wells sampled (012, 013, 014) were located on site. Two of the well samples contained copper (12 and 18 $\mu g/l$) and the sample from the well at the quarry office contained 8.6 $\mu g/l$ lead. The quarry office well is not used for drinking water.

The well sample from the (b) (9) residence (010) which is located at the southeast corner of the quarry contained 9 μ g/l chromium, 20 μ g/l copper and had a conductivity of 1,300 μ mohs. Approximately one mile northwest of the quarry, a background well sample was collected at the Moses residence (018). This sample contained 11 μ g/l copper, undetected levels of chromium, and had a conductivity of 640 μ mohs. The Umthun Trucking terminal well sample (003) was found to contain 28 μ g/l chromium and 13 μ g/l copper, and had a conductivity of 500 μ mohs and a pH of 7.6. Previous problems with this well, which is cased through the abandoned portion of the Linwood Quarry used to vent the flue gases from the kilns, initiated the investigative work at this site.

The sulfate and chloride anion analyses of the well samples found only one well sample that exceeded the Secondary Maximum Contaminant Level (SMCL) for sulfate. The city of Buffalo well #2 contained 268 mg/l sulfate. None of the other wells had sulfate levels over 200 mg/l or chloride levels over 100 mg/l (Table 3).

Mine Waters

Sample 016, collected from the discharge pond, had concentrations of copper at 10 μ g/l and chromium at 16 μ g/l; this sample had the highest chloride (112 mg/l) and second highest sulfate (374 mg/l) level of all the water samples. Sample 016 had a pH of 9.8 which is distinctly higher than any of the other water samples, and a conductivity of 1,000 μ mohs.

The remaining mine water samples have levels of metals and anions comparable to the background surface water and ground water values.

Soil, Sediment, and Ash Samples

To better characterize the soil, sediment, and ash compositions of the samples collected during this project an average soil composition was tabulated for the elements of concern. This average soil was tabulated based on analyses of uncultivated B-horizon soils within the United States (Connor and Shacklette 1975). The mean values are listed at the top of Table 4.

Anion tests for sulfide were performed on the ash, sediment, and soil samples. Sulfur concentrations were not reported for the average soil. Background values ranging from 10.6 mg/kg to 21.2 mg/kg were reported for the soils and sediments collected for this project (Table 4). No consistent trend of increasing concentrations for downgradient samples was evident, and only one of the ash samples (031 at 53 mg/kg) had a sulfide concentration which exceeded background levels.

All of the arsenic, barium, chromium, and lead, and all but one of the copper concentrations (038) are less than average levels for soil. Conversely, all of the silver concentrations, all but one of the selenium values, and all of the cadmium values reported are slightly greater than the average soil concentrations for an uncultivated B-horizon soil.

Three sediment samples were collected along Donaldson Creek: a background sample (043) above the Scott County landfill; one sample between the landfill and quarry (039); and a third sample (042) from downgradient of the quarry at its confluence with the Mississippi River. No trend of increased downgradient concentration was observed for any of the elements of concern. The concentrations are below the average soil levels (Table 4).

Moore Creek flows in a southerly direction past the ash piles and into the Mississippi River. A sample was collected upgradient (036) and downgradient (038) of the ash piles. The metals and sulfide levels display a distinct trend of increased concentration from the upgradient to the downgradient sample. The concentrations of lead, selenium, and silver in the downgradient sample are more than 1,000% above average

soil levels, and more than 300% higher than the concentrations observed in the background samples from Donaldson and Moore creeks (Table 4).

The Extraction Procedure Toxicity test (EP Tox) (CFR40 Part 261.24) was performed on the soil, sediment, and ash samples (Table 5). The elements of concern were detected at levels well below those established by the EPA as action levels. Thallium was detected in some of the samples in the lower parts per billion range. No EP Tox level has been established for thallium.

SUMMARY AND CONCLUSIONS

Work at the Linwood Quarry (formerly Umthun Trucking) site was initiated by complaints from workers at the terminal concerning the well water. Initail analyses by the county and state disclosed levels of chromium, copper, lead, zinc, and vanadium in the parts per million ranges and a pH of 2.7. Further work by state and local agencies revealed that the Umthun well penetrated through the mine works of the Linwood Quarry which had been closed off for use as a venting/precipitating system for the flue gases from the lime kilns. The acidic nature of the flue gases may have caused corrosion of the well casing, resulting in elevated metals levels and the low pH of the well water. The Umthun well has since been re-cased and grouted.

Analyses of the Umthun well sample collected by the FIT for this project found 28 $\mu g/l$ chromium, 13 $\mu g/l$ copper, 89 $\mu g/l$ barium, and 1 mg/l chloride and 22 mg/l sulfate. All of these concentrations are below the MCLs and SMCLs established by the EPA. Field measurements recorded a pH of 7.6 and 500 μ mohs for conductivity.

Water samples from streams, wells, and mine waters were collected to characterize current site conditions. The total metals and anion analyses of the surface water samples revealed only one element of concern: chromium levels on Donaldson Creek displayed a clear trend of increasing concentration from the upgradient background sample to the downgradient sample. However, detected concentrations were below the recommended MCLs.

Using the (b) (9) well (018) as background, the levels of chloride, sulfate, and conductivity are elevated in the (b) (9) well (010) and in at least two of the on-site wells (013 and 014). The (b) (9) r well is located at the southeast corner of the Linwood Quarry. The upgradient Scott County landfill may also have some effect on this location.

Compared to the background surface and well water samples, one mine water sample (016) displayed elevated chloride, sulfate, and conductivity levels. This sample, collected from the discharge pond that occupies the abandoned surface quarry, also had a pH of 9.8 which is anomalously high. The water in the discharge pond is used to wash down the aggregate from the mine to reduce dust problems.

Compared to average soils and background soils, the kiln ash samples collected for this project had elevated concentrations of

silver, selenium, and cadmium. One ash sample also displayed an elevated sulfide concentration.

The results of the soil and sediment analyses reveal that the sediment collected downstream from the ash piles has elevated concentrations of silver, selenium, lead, and cadmium. These elevated levels appear to be the result of mechanical transport of ash particulates downstream and not related to solution/precipitation processes of the metals. This is inferred because the surface water analysis at this location displayed relatively low metals concentrations.

The amount of sulfur dioxide and nitrogen oxides that are being vented from the kilns into the abandoned mine area at the Linwood Quarry may also be significant. Analyses provided by Linwood Quarry state that 329 lbs/hour of sulfur dioxide and 123 lbs/hour of nitrogen oxides are vented into the abandoned mine works (Table 5). The effect of the influx of these very reactive oxides on the limestone of the Davenport Formation, which is a part of the regionally important Devonian aquifer, is not fully known at this time.

The FIT could not collect samples in the abandoned mine area because the kilns and blowers were in operation. Gaillard Krewer informed the FIT that the kilns were scheduled to be down for maintenance at a later date. Krewer indicated that the Iowa Department of Natural Resources (IDNR) was regularly monitoring the emissions from the mine vent for opacity. He also pointed out the new air monitoring station being emplaced by IDNR just northeast of the mine vent. Later discussions indicated that Krewer was in contact with IDNR concerning permits for the use of the discharge pond water and the return of dustladen effluents to this receptor (Krewer 1989b). He also indicated at this time that no state or federal agency had collected samples from the mine vent area to document existing conditions.

The Linwood Quarry site in Buffalo, Iowa, is a relatively complex project with several possibly interacting processes occurring. Factors potentially influencing the ground water at this site include the influx of flue gases into the abandoned mine works; possible percolation of high pH water from the discharge pond into the aquifer, as well as leachate from the Scott County landfill which overlies a portion of the Linwood Quarry. Components which may be affecting air quality would include the flue gases venting from the abandoned mine works into the atmosphere, and the possibility of airborne particulates from the surface dumped ash. There is also a coal-fired electric generating plant located adjacent to the quarry.

Attachments: Bibliography

Figure 1: Site Location Map Figure 2: Sample Location Map

Table 1: Ash, Sediment, and Soil Sample Summary

Table 2: Mine, Surface, and Well Water Sample Summary

Table 3: Water Sample Analytical Summary

Table 4: Soil, Sediment, and Ash Analytical Summary

Table 5: Analysis of Lime Kiln Flue Gases Chain-of-Gustody and Field-Sheets EPA Data Transmittals EPA Site Investigation Form 2070-13 Technical Directive Document (TDD)

BIBLIOGRAPHY

- Connor, Jon J., and Shacklette, Hansford T., 1975, Background
 Geochemistry of Some Rocks, Soils, Plants, and Vegetables in the
 Conterminous United States, Geological Survey Professional Paper
 574-F, U.S. Government Printing Office, Washington, D.C.
- Ecology and Environment, Inc., 1989, Work Plan for the Screening Site Inspection of Umthun Trucking, TDD# F-07-8809-008.
- U.S. Environmental Protection Agency, EPA Regulatory Status for Chemicals in Drinking Water, Washington, D.C., March, 1988, Draft.
- Iowa Geological Survey, 1984, Miscellaneous Map Series 10: Silurian Devonian Aquifer of Iowa, Iowa City, Iowa.
- Krewer, Gaillard, May 23, 1989a, Director of Mine Operations, Linwood Quarry, Buffalo, Iowa, on-site interview with Wes McCall, E & E/FIT.
- Krewer, Gaillard, November 14, 1989b, Director of Mine Operations, Linwood Quarry, Buffalo, Iowa, telephone interview with Wes McCall, E & E/FIT.
- U.S. Geological Survey, 1970, 7.5 Minute Series Topographic Map, Andalusia, Iowa, Quadrangle.

Table 1 Ash, Sediment, and Soil-Sample Summary Linwood Quarry (formerly Umthun Trucking) Buffalo, Iowa E & E/FIT, May, 1989 Sample Series DC943

Sample	Description	Location			
031	Kiln Ash	~50 ft. S of quarry vent N of Umthun			
032	Kiln Ash	~150 ft. SE of quarry vent			
033	Kiln Ash	E side of hilltop, South of quarry vent			
034	Kiln Ash	~100 ft. down hillside (SE) of sample 033			
034D	Kiln Ash	Duplicate of 034			
035	Bkg. Soil	Hilltop 250 feet north o quarry vent			
036	Bkg. Sediment	Moore Creek, NNE of ash piles, upstream			
037	Soil	50 feet N of Umthun well			
038	Sediment	Moore Creek downgradient Umthun terminal			
039	Sediment	Donaldson Creek between Landfill and Linwood Quarry			
040	Kiln Ash	Linwood Quarry Limeplant South blower at kilns			
041	Kiln Ash	Limeplant, cooling rollers overflow			
042	Sediment	Confluence of Donaldson Creek and Mississippi River			
043	Bkg. Sediment	North of landfill on Donaldson Creek			
044	Soil	Moses Residence			

Note: All samples consisted of 5 aliquots collected from 0 to 6 inches. See Figure 2 for sample locations.

Table 2 Mine, Surface, and Well-Water-Sample Summary Linwood Quarry (formerly Umthun Trucking) Buffalo, Iowa E & E/FIT, May 1989

Sample Series DC943

			Temp		nductivity
Sample			°C	pН	<u>µmohs</u>
001	Surface Water	Background on Moore Creek, NE of Quarry vent	NR	NR	NR
002F		Field Blank			
003	Well Water	Umthun terminal	25°	7.63	500
004	Surface Water	Moore Creek downstream from ash piles	NR	NR	NR
005	Well Water	Scott County Landfill	13°	7.67	500
006	Surface Water	Donaldson Creek between landfill and quarry	NR	NR	NR
007	Surface Water	Donaldson Creek North (upstream) of landfill	NR	NR	NR
800	Well Water	(b) (9)	(b) (9)		
009	Well Water	(b) (9)	(b) (9)		
010	Well Water	(b) (9)	(p) (a)	(b) (9)	(b) (9)
011	Surface Water	Confluence of Donaldson Creek with Mississippi River	17°	6.5	700
012	Well Water	Well head at Linwood Limeplant	16°	6.7	500
013	Well Water	Bathhouse at Linwood Quarry N. of Hwy 22	16°	7.3	900

Table 2 (Continued)

Sample	# Description	Location	Temp °C	рН	Conductivity µmohs
014	Ground Water	Linwood Quarry office before filter system	17°	7.1	800
015	Mine Water	Linwood Mine, 2nd level, under mine vent area	19 ° *	6.65	600
016	Mine Water	Discharge pond in abandoned quarry works	22°*	9.8	1000
017	Mine Water	Pumped discharge from well head outlet pipe at surface evap. pond	12.5°	6.6	640
017D	same as 017	same as 017	12.5°	6.74	640
018	Ground Water	(b) (9)	(b) (9)	(b) (9)	(b) (9)
019	Ground Water (chlorinated)	City of Buffalo Well #2	14.5°	6.20	900

Note: See Figures 1 and 2 for sample locations.

NR - Not recorded

^{*}Measurement recorded 30 minutes after sample was collected.

Table 3
Water Sample Analytical Summary
Linwood Quarry (formerly Umthun Trucking)
Buffalo, Iowa
E & E/FIT, May 1989
Sample Series DC943

Sample #	Ba	Cr	Cu	Pb		Sulfate
MCL	1000	50	1000	10	250* mg/l	250*mg/l
		SURF	ACE VATE	R (Moore Creek	•	
001	33J	12	<25	<5.0	40	394
004	50J	<10	<25	<5.0	40	334
			(Donalds	son Creek)		
007	63J	<10	<25	<5.0	66.2	155
006	74J	9J	<25	<5.0	64.8	258
011	54J	28	<25	<5.0	55.6	258
	Gl	ROUND	WATER (we	ells) resident	ial	
018	48J	<10	11	<5.0	1.3	12
800	98J	<10	<25	<5.0	2.1	37 . 3 ·
009	100J	<10	<25	<5.0	11.3	37.9
010	62J	9 J	20J	<5.0	190	180 、
			off	site		
019	120J	<10	<25	<5.0	27	268
005	110J	<10	<25	<5.0	0.55	20.2
003	89J	28	13J	<5.0	1.01	21.8
			on	site	•	
012	61J	<10	<25	<5.0	14	50
013	24J	<10	18J	<5.0	84	181
014	43J	<10	12J	8.6	61.6	135
			MINE	WATERS		
015	40J	<10	<25	<5.0	24.4	142
016	34J	16	10J	<5.0	112	374
017	79J	<10	<25	<5.0	7	69
017D	81J	16	<25	<5.0	7.2	68
			FIEL	D BLANK		•
002	U	<10	<25	0.4		

MCL = Maximum contaminant levels established by the EPA in 1988; concentrations are $\mu g/l$.

NOTE: Only detected levels are reported; see data transmittal for complete analytical results. All concentrations are reported in micrograms per liter ($\mu g/l$). See Figures 1 and 2 for sample locations.

J - The associated numeric value is an estimated quantity (see data transmittal).

^{*}Secondary MCLs for drinking water.

Table 4
Soil, Sediment, and Ash Analytical Summary
Linwood Quarry (formerly Umthun Trucking)
Buffalo, Iowa
E & E/FIT, May 1989
Sample Series DC943

	Elemen	ıt							
Sample #	As	Ва	Cd	Cr	Cu	Pb	Se	Ag	<u>S-</u>
SOIL*	9.3	372	<0.1	46.1	17.3	19.6	0.43	<0.5	**
			KILN A	SH (old	l ash pi	les)			
031	5.9J	53J	0.6J	15	38J ⁻	12	0.69J	6	53
032	5J	49J	0.53J	12	4.8J	10	0.75J	5.1	21.2
033	4.9J	36J	0.81J	12	2.2J	7.4	0.65J	4.3	10.6
034	5J	52J	<1.3	11	3.4J	6.1	0.62J	5.2	10.6
034D	5.4J	57	0.48J	12	5.3J	6.3	0.6J	5.3	21.2
			, ,	, , ,					
040	2 (1	<i>(</i> 7	•		ln ash)		1 /	2.0	01 0
040	3.6J	67	<1.0	6.8	14J	13	1.4	2.9 4	21.2
041	3.2J	68	<1.0	6.8	14J	8.1	0.38J	4	10.6
			SEDIM	ENTS (M	loore Cı	eek)			
036	4.1J	160	0.87J	8.7	<7.3	6.Ś	0.23J	<2.9	10.6
038	6.1J	100	1.1J	18	<9.2	79	4.5	5.5	21.2
					<i>-</i> ,				
			•		on Creek	•		40. 7	24 2
043	3.7J	775	<1.4	7.9	<6.8	9.4	0.38J	<2.7	21.2
039	5.9J	86	0.53J	-	<6.6	9.5	0.4J	<2.6	21.2
042	4.3J	79	<1.5	11	<7.3	9.4	0.44J	<2.9	10.6
				S0]	TLS.				
044	5.3J	270	0.48J	15	<6.0	24	0.41J	<2.4	10.6
035	9.6J	140	<1.2J	21	<6.0	18	0.41	<2.4	10.6
037	5J	110	0.45J	16	<5.7	14	0.41J	<2.3	10.6
		-	- · · - -						

NOTE: Only detected levels are reported. See Figure 2 for sample locations and the attached data transmittal of complete analytical results. All concentrations are reported in miligrams per kilogram (mg/kg).

^{*} SOIL is a mean of values from uncultivated B-horizon soil from the U.S. (Connor & Shacklette, 1975). All concentrations are mg/kg.


^{**} No values available for average soil.

J - The associated numeric value is an estimated value (see data transmittal).

Table 5
Analysis of Lime Kiln Flue Gases
Linwood Quarry
Buffalo, Iowa


(Source	Carbon Dioxide	Oxygen %	Nitrogen %	Volume ACFM	Volume SCFM	Stack Gas	Ductcross Sectional Area Ft 2	Particulate Grains/SCF	Particulate lbs/hr.	Sulfer Dioxide lbs/hr.	Nitroge Oxide
Main flue				ACFM	SCFM	- r	Alea PC 2	Grains/3Cr	105/111.	105/11.	105/111
duct to make the shaft aft	nine										
Cyclones	10.4	10.0	79.6	151,757	5,287.360	405	38.48	0.88	701.56	329.69	123 . 17
#1 Kiln											
Before Ex Fan and	chaust										
Cyclose											
System	8.0	14.5	77.5	41,007	1,198,215	601	10.56	0.34	60.01	74.01	43:-44
2 Kiln-E	Before										
Exhaust E and Cyclo											-
System	13.3	11.0	75.7	46,781	1,339,953	620	11.92	3.22	663.16	252.52	!
3 Kiln-A	After										
xhaust F Before Cy											
ystem	13.4	9.5	77.1	52 685	1,763,856	475	12.05				

Source: Linwood Mining and Minerals.



WASTE SITE TRACKING NO.: IA0238
PREPARED BY: LEE ROBERTSON FIT 1989
SOURCE: USGS ANDALUSIA, IA 1970 QUAD

Figure 1: Site Location with Well Sample Locations



POTENTIAL HAZARDOUS WASTE SITE I. IDENTIFICATION 01 STATE 02 SITE NUMBER 090852297 EPA SITE INSPECTION REPORT PART 1 - SITE LOCATION AND INSPECTION INFORMATION II. SITE NAME AND LOCATION 02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER 01 SITE NAME (Legal, common, or descriptive name of site) Linwood Quarry (formerly Umthun Trucking) Route 22 07 COUNTY 08 CONG 04 STATE 05 ZIP CODE 06 COUNTY 03 CITY IA 52728 Buffalo 09 COORDINATES 10 TYPE OF OWNERSHIP (Check one) LATITUDE X A. PRIVATE ___ B. FEDERAL _____ C. STATE ___ D.COUNTY E. MUNICIPAL LONGITUDE 41° 27′54.8"N 090° 41′04.5"W ____f. OTHER __ G. UNKNOWN III. INSPECTION INFORMATION 01 DATE OF INSPECTION 03 YEARS OF OPERATION 02 SITE STATUS X ACTIVE 1940 present 5/22/89 __ | ___INACTIVE BEGINNING YEAR ENDING YEAR MO/DAY/YR 04 AGENCY PERFORMING INSPECTION (Check all that apply) A. EPA X B. EPA CONTRACTOR Ecology & Environ. C. MUNICIPAL D. MUNICIPAL CONTRACTOR (Name of firm) E. STATE F. STATE CONTRACTOR G. OTHER (Name of firm) (Specify) 05 CHIEF INSPECTOR 06 TITLE 07 ORGANIZATION 08 TELEPHONE NO. Wesley McCall Environmental Specialist E & E/FIT (913)432-9961 09 OTHER INSPECTORS 10 TITLE 11 ORGANIZATION 12 TELEPHONE NO. Gayle Hubert Geologist E & E/FIT (913)432-9961 Rob Parsons E & E/FIT (913)432-9961 Chemist Debbie Fischer Geologist E & E/FIT (913)432-9961 15 ADDRESS 401 E. Front St. Davenport 13 SITE REPRESENTATIVES INTERVIEWED 14 TITLE 16 TELEPHONE NO. Gaillard Krewer Mine Engineer (319)324-1931 401 E. Front St. Davenport Alvin Lee Assistant Plant Mgr. (319)324-1931 401 E. Front St. Davenport Bob Niemala (319)324-1931 Mine Manager Umthun Terminal Buffalo, Iowa Kevin Powell Terminal Manager (319)381-1123 17 ACCESS GAINED BY (Check one) 18 TIME OF INSPECTION 19 WEATHER CONDITIONS x PERMISSION Clear, Sunny, '60°F daylight WARRANT IV. INFORMATION AVAILABLE FROM 01 CONTACT 03 TELEPHONE NO. 02 OF (Agency/Organization) Pete Culver Region VII, U.S. EPA Superfund (913)236-2836

06 ORGANIZATION

FIT

E & E

07 TELEPHONE NO.

913-432-9961

08 DATE 11/17/89

Wesley McCall

04 PERSON RESPONSIBLE FOR SITE INSPECTION FORM 05 AGENCY

	_		POTENTIAL HAZARI	OOUS WASTE SITE		i	I. IDENTIFI	CATION
BPA			SITE INSPECT	ION REPORT		i	01 STATE	2 SITE NUMBER 1
			PART 2 - WASTE	INFORMATION		ı	IA	D90852297
II. WASTE STA	II. WASTE STATES, QUANTITIES, AND CHARACTERISTICS							
O1 PHYSICAL S	TATES	02 WAS	TE QUANTITY AT SI	TE 03 WASTE CHARA	CTERISTICS			
(Check all th	at apply)	(Measu	res of waste quant ust be independent	ti- (Check all that	t apply)			
X A. SOLID	E. SLURRY	ties m	ust be independent	X A TOYIC	E. 5	SOLUBLE	I. 1	HIGHLY VOLATILE
I 	FINES F. LIQUID	l		B. CORROSI				
C. SLUDGE	G. GAS		TONS	C. RADIOAC				REACTIVE
D. OTHER		CURTC	YARDS ~100,000	X D. PERSIST				NCOMPATIBLE
		COBIC	1ARDS 100,000	- 		IGNIINDL		NOT APPLICABLE
(Specify) MO. OF DRUMSM. NOT APPLICATE						AOI APPLICABLE		
III. WASTE TY	PE							
CATEGORY	SUBSTANCE NAME	T	01 GROSS AMOUNT	02 UNIT OF MEASU	RE 03 COM	MENTS		
SLU	SLUDGE				- T	_		<u> </u>
OLW	OILY WASTE							
SOL	SOLVENTS							
PSD	PESTICIDES							
occ	OTHER ORGANIC CHEM	ICALS					1	
IOC	INORGANIC CHEMICAL	<u> </u>						
ACD	ACIDS							
BAS	BASES							
MES	HEAVY METALS		unknown		Lime k	iln fly	ash	
				the sited CAS Numb		- LIN LLY	4411	
IV. HAZARDOUS	SUBSTANCES (See A	ppenarx	for most frequent	ETY CICUA CAS NUMB	ers/	Τ	 -,	AC WESSELES AS
01 CATEGORY	02 SUBSTANCE NAM	E	03 CAS NUMBER	04 STORAGE/DISPO	SAL METHOD	05 CONC	ENTRATION	06 MEASURE OF CONCENTRATION
MES	Silver		7440-22-4	Surface dumped		<10		mg/kg
	Cadmium		7440-43-9	Surface dumped		~1	····	mg/kg
	Selenium		7446-08-4	Surface dumped <2				mg/kg
	Lead		7439-92-1	Surface dumped (20				mg/kg
						t		
			·····	· · · · · · · · · · · · · · · · · · ·				
				·				
						†	·	
				· · · · · · · · · · · · · · · · · · ·				
						 		
						 		<u> </u>
						ļ		
<u> </u>						 		ļ
<u> </u>						ļ		
				<u> </u>		 		
				 		<u> </u>		ļ
	L			<u> </u>		L		L
	S (See Appendix for							<u>.</u>
CATEGORY	01 FEEDSTOCK	NAME	02 CAS NUMBER	CATEGORY	01 FEED	STOCK N	AME 0	2 CAS NUMBER
FDS				FDS				
FDS				FDS				
FDS				FDS				
FDS				FDS				
VI. SOURCES	S OF INFORMATION (C	ite spe	cific references,	e.g., state files	, sample an	alysis,	reports)	
,								
Ecology and	Environment, Inc	Field	Investigation Tea	m (E & E/FIT), Nov	ember, 1989	, Data S	Summary for	the Linwood
Quarry sit	te, TDD #F-07-8809- shall, 1985, Handbo	008. ok of T	oxic and Hazardou	s Chemicals and Ca	rcinogens,	Park Ric	ige, New Je	rsey.
Ecology and Quarry Si	Environment, Inc., te, TDD #F-07-8809-	Field 008.	Investigation Tea	m (E & E/FIT), Jun	u 14, 198 9,	Trip Re	eport for the	he Linwood
Ecology and Inspection	Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), November, 1989, Data Summary for the Linwood Quarry site, TDD #F-07-8809-008. Siting, Marshall, 1985, Handbook of Toxic and Hazardous Chemicals and Carcinogens, Park Ridge, New Jersey. Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), June 14, 1989, Trip Report for the Linwood Quarry Site, TDD #F-07-8809-008. Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), May 8, 1989, Work Plan for the Screening Site Inspection of the Umthun Trucking/Linwood Quarry site, TDD #F-07-8809-008.							

	POTENTIAL HAZ	I. IDENTIFICATION			
EPA		ECTION REPORT	01 STATE	02 SITE NUMBER D90852297	
PART 3 -		AZARDOUS CONDITIONS AND INCIDENTS			
01 X A. GROUNDWATER CONTAMINATION		2 x OBSERVED (DATE: 8/25/83)	POTE	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED:		4 NARRATIVE DESCRIPTION			
Heavy metals contamination of priva well has been re-cased and is no lo	•	and the same of th	<50. Th€		
		2 00000000 (00000	DOME	TARTAL ALLEGO	
01B. SURFACE WATER CONTAMINATION		OBSERVED (DATE:)	POTE	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED: None known or observed to date.		4 NARRATIVE DESCRIPTION			
01C. CONTAMINATION OF AIR	0	2 OBSERVED (DATE:)	POTE	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED:	0	4 NARRATIVE DESCRIPTION			
None known or observed to date.					
01 D. FIRE/EXPLOSIVE CONDITIONS	0	2 OBSERVED (DATE:)	POTI	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED:	_	4 NARRATIVE DESCRIPTION	_		
None known or observed to date.					
01		2	2000	NOTAL LINGER	
01E. DIRECT CONTACT		2 OBSERVED (DATE:) 4 NARRATIVE DESCRIPTION	· POT!	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED: None known or observed to date.		4 NARRATIVE DESCRIPTION			
none known of observed to date.					
01 X F. CONTAMINATION OF SOIL	0	2 X OBSERVED (DATE: 5/22/89)	POTI	ENTIAL ALLEGED	
03 AREA POTENTIALLY AFFECTED: 3	0	4 NARRATIVE DESCRIPTION			
Area covered by kiln fly ash dumple	(Acres) ed on soil surfac	e.			
01 X G. DRINKING WATER CONTAMINATION	ON 0	2 X OBSERVED (DATE:)	POT	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED:	unknown 0	4 NARRATIVE DESCRIPTION			
Private well of Umthun Trucking ter ground water above.	minal contaminat	ed by heavy metals pH ~2.7, popula	tion affe	ted probably <50. See	
01 _ x H. WORKER EXPOSURE/INJURY	0	2 OBSERVED (DATE:)	POT	ENTIAL X ALLEGED	
03 WORKERS POTENTIALLY AFFECTED: unk	nown0	4 NARRATIVE DESCRIPTION	_		
Truck drivers stay overnight at ter probably <50. The well has been re	minal, showered cased and is no	in and drank contaminated well wat longer contaminated.	er. Popu	lation affected	
01 I. POPULATION EXPOSURE/INJURY	0	2 OBSERVED (DATE:	POT	ENTIAL ALLEGED	
03 POPULATION POTENTIALLY AFFECTED:		4 NARRATIVE DESCRIPTION			
No one other than workers at termin					

,	POTENTIAL HAZARDOUS WASTE SITE	I. IDENTIFICATION		
EPA .	SITE INSPECTION REPORT	01 STATE 02 SITE NUMBER D90852297		
	DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS			
II. HAZARDOUS CONDITIONS AND INCID	The state of the s			
01J. DAMAGE TO FLORA	02OBSERVED (DATE:	POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION				
None known or observed to date.	Annual Control of the			
01 K. DAMAGE TO FAUNA	O2OBSERVED (DATE:) · POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION (Include n None known or observed to date.	ame(s) or species;			
none known of observed to date.	•			
01L. CONTAMINATION OF FOOD CHAI	N 02 OBSERVED (DATE:) POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION				
None known or observed to date.				
01 X M. UNSTABLE CONTAINMENT OF WA	<u> </u>) POTENTIAL ALLEGED		
(Spills/runoff/standing liquids/l	-			
03 POPULATION POTENTIALLY AFFECTED: Surface dumped fly ash, no liner,		·		
Surface dumped fly agn, no liner,	no containment of diking.	•		
	0.05.402			
01 X N. DAMAGE TO OFFSITE PROPERTY	02 <u>X</u> OBSERVED (DATE: <u>8/25/83</u>) POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION	into well. Con ground unter above			
Heavy metals contamination of priv	ate well. See ground water above.			
O1O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPB	02 OBSERVED (DATE:) POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION				
None known or observed to date.				
		•		
01 X P. ILLEGAL/UNAUTHORIZED DUMPI	NG 02 OBSERVED (DATE:) X POTENTIAL ALLEGED		
04 NARRATIVE DESCRIPTION				
Linwood Quarry is presently in a dinto quarry pond.	discussion with IDNR concerning permitting for dump	oing dust-laden mine water		
	·			
05 DESCRIPTION OF ANY OTHER KNOWN,	POTENTIAL, OR ALLEGED HAZARDS .			
III. TOTAL POPULATION POTENTIALLY	AFFECTED: unknown			
IV. COMMENTS				
V COMPARE OF THEODMANTON (C:+	parific references and state files sample and	lucic reports)		
EPA, 1983 to 1988	pecific references. e.g., state files, sample anal	rysis, reports;		
E & E/FIT, November, 1989 Robertson, 1983				

		POTE	NTIAL HAT	EARDOUS 1	MASTE SIT	В	ľ	DENTIFICATION
EPA		;	SITE INS	PECTION 1	REPORT		01 ST	ATE 02 SITE NUMBER D90852297
	PART	: 4 - Pi	ERMIT ANI	D DESCRI	PTIVE INF	ORMATION	10	
II. PERMIT INFORMATION								
01 TYPE OF PERMIT ISSUED	02	PERMI	T NUMBER	03 DAT	E ISSUED	04 EXPIRATION DATE	E 05 C	COMMENTS
(Check all that apply)	İ					Į		
A. NPDES		•	· .					
B. UIC								
C. AIR							ŀ	
D. RCRA								
E. RCRA INTERIM STATUS								
F. SPCC PLAN								
X G. STATE (Specify)	υ	ınknown						
H. LOCAL (Specify)								
I. OTHER (Specify)								
J. NONE			-					
III. SITE DESCRIPTION				1			-1	
01 STORAGE/DISPOSAL (2 AMOUN	VT 03	UNIT OF	MEASURE	04 TREAT	MENT		05 Other
(Check all that apply)					(Chec	k all that apply)		
A. SURFACE IMPOUNDMENT					A. 1	none NCINERATION		
X B. PILES	100,000		cubic yas	rds	B. U	NDERGROUND INJECTI	OM	A. BUILDINGS ON SITE
C. DRUMS, ABOVE GROUND					l —	HEMICAL/PHYSICAL		l
D. TANK, ABOVE GROUND					l —	IOLOGICAL		
					I —		_	06 AREA OF SITE
E. TANK, BELOW GROUND						ASTE OIL PROCESSING	j .	
F. LANDFILL		 .				OLVENT RECOVERY		(Acres)
G. LANDFARM					G. o	THER RECYCLING/REC	OVERY	Area of mine works.
H. OPEN DUMP					н. о	THER		l .
I. OTHER					ļ	(Specify)		
(Specify)								
07 COMMENTS					i			
					•			
IV. CONTAINMENT								
01 CONTAINMENT OF WASTES (Che	ck one)							
A. ADEQUATE, SECURE	F	B.MODER	ATE	X C.IN	ADEQUATE,	POORD. I	NSECURI	E, UNSOUND, DANGEROUS
02 DESCRIPTION OF DRUMS, DIKI	NC T TNI	EDC DA	DDTEDC	FTC				
					- L - G 3			dini bandana ba
Approximately 3 acres cover prevent off site migration	ad with via surf	face ru	noff, or	recharg	e infiltr	ation.	rs, no	diking of Darriers to
-								
V. ACCESSIBILITY			-		 			
01 WASTE EASILY ACCESSIBLE:	X YES	NO						
02 COMMENTS								
Surface dumped ash is not c	overed,	inadeq	uate fen	cing, op	en gates.			•
VI. SOURCES OF INFORMATION (
Ecology and Environment, In Quarry Site, TDD #F-07-88 Ecology and Environment, In Krewer, Gaillard, November	C., Fiel	ld Inve	stigatio	n Team (E & E/FIT), November, 1989,	Data	Summary for the Linwood
Ecology and Environment, In	ç, Jun:	e 14, 1	989, Tri	p Report	for the	Linwood Quarry Sit	e, TDD	#F-07-8809-008.
Riewer, Gaillard, November	10, 1985	, pers	OUST COM	municat1	on, Mine	Engineer, Linwood	Quarry	, Bullato, Iowa.

Umthun Trucking

<u> </u>				Omendii II de	
	POTENTIAL HAZARDOU	I. IDENTIFICATION			
BPA	SITE INSPECTION	N REPORT		01 STATE 02 SITE NUMBER	
PART	5 - WATER, DEMOGRAPHIC,	AND ENVIRONMENT.	AL DATA	IA D90	852297
II. DRINKING WATER SUPPLY		· · · · · · · · · · · · · · · · · · ·			
	1	· · · · · · · · · · · · · · · · · · ·	 _	I	
01 TYPE OF DRINKING SUPPLY (Check as applicable)	02 STATUS			03 DISTANCE TO	SITE
SURFACE WELL	ENDANGERED	AFFECTED MO	NITORED	Į.	
COMMUNITY A. B. X			c. x	A. ~3.5	(mi)
NON-COMMUNITY C. D. X	A		F.	B. <0.1	(mi)
B. <u>A</u>	D		· · - <u> </u>	1	
III. GROUNDWATER					
01 GROUNDWATER USE IN VICINITY (C	neck one)				
X A. ONLY SOURCE FOR B. DRI		C, COMMERCIA	L, INDUSTRIA	L IRRIGATION	D. NOT USED,
	sources available)	(Limited of	ner sources	avallable;	UNUSABLE
COMMER (No ot	CIAL, INDUSTRIAL, IRRIGA her water sources availa	TION ble)			,
					
02 POPULATION SERVED BY GROUND WA	rer ~4400	03 DISTANCE TO N	EAREST DRINK	ING WATER WELL	<u>(0.1</u> (mi)
04 DEPTH TO GROUNDWATER 05 DIRECT	FER 07 POTEN	TIAL YIELD 08 S	OLE SOURCE AOUIFER		
200 to 350 (ft) SSE		OF CONCERN (f) OF AQ	IITPED (YES X NO
200 00 330 (10)		(2		(gp = /	
09 DESCRIPTION OF WELLS (Includin	g usage, depth, and loca	tion relative to	population	and buildings)	
Buffalo, Iowa municipal well, 4	05 feet deep, west edge	of town.			
10 RECHARGE AREA		11 DISCHARGE ARE	A	•	
YES COMMENTS unknown		YES COMM	ENTS unkn	own	
— NO		NO NO			
IV. SURFACE WATER					
01 SURFACE WATER USE (Check one)					
X A. RESERVOIR, RECREATION DRINKING WATER SOURCE	B. IRRIGATION, ECONOMICA IMPORTANT RESOURCES	LLYC. COMME	RCIAL, INDUS	TRIALD. NO	T CURRENTLY USED
02 AFFECTED/POTENTIALLY AFFECTED					
NAME:			AFFECTED	DISTAN	CE TO SITE
Mississippi River				On river	
Madada Alan					(mi)
					(mi)
					\\
V. DEMOGRAPHIC AND PROPERTY INFO	RMATION				
01 TOTAL POPULATION WITHIN			02 DISTANCE	TO NEAREST POPU	LATION
ONE (1) MILE OF SITE TWO (2)	MILES OF SITE THREE (3) MILES OF SITE	A	djacent to site	(mi)
A. ~215 B. ~1,2	00 C. ~440	0			
		OF PERSONS			
03 NUMBER OF BUILDINGS WITHIN TWO	···		NEAREST OFF	-SITE BUILDING	
~300		<0.1		(mi)	
05 POPULATION WITHIN VICINITY OF	SITE (Provide narrative	description of n	ature of pop	ulation within	vicinity of site,
The majority of the population w scattered rural homes. The subu	rban and urban areas of	Davenport, Iowa,	are outside	of the three-m	ile radius.
		-			

Umthun Trucking

	POTENTIAL HAZA	I. IDENTIFICATION				
EPA	SITE INSPE	01 STATE 02 SITE NUMBER D90852297				
	PART 5 - WATER, DEMOGRAP	HIC, AND ENVIR	ONMENTAL DATA	IA B30032237		
II. ENVIRONMENTAL INFO	PRMATION		 -			
01 PERMEABILITY OF UNS	ATURATED ZONE (Check one)					
A. 10 ⁻⁶ - 10 ⁻⁸ cm,	/sec $XB. 10^{-4} - 10^{-6}$ cm/sec	c10 ⁻⁴ _	10 ⁻³ cm/secI	D. GREATER THAN 10 ⁻³ cm/sec		
02 PERMEABILITY OF BEDI	ROCK (Check one) unknown					
A. IMPERMEABLE	B. RELATIVELY IMPERMEAB		RELATIVELY PERMEABI			
	$(10^{-4} - 10^{-6} \text{ cm/sec})$	(1)	$0^{-2} - 10^{-4} \text{ cm/sec}$	(Greater than 10 ⁻² cm/sec)		
03 DEPTH TO BEDROCK	04 DEPTH OF CONTAMINATED SOIL	ZONE 0	5 SOIL pH			
unknown (ft)	unknown (ft)		unknown	!		
06 NET PRECIPITATION	07 ONE YEAR 24 HOUR RAINFALL	08 SLOPE SITE SLOPE	I DIRECTION OF SITE	E SLOPE TERRAIN AVERAGE SLOPE		
32 (in)	2.75 (in)	5 to 40 %	south	est. 8 %		
09 FLOOD POTENTIAL part	l tially 10					
SITE IS IN 100	YEAR FLOOD PLAN SITE I	S ON BARRIER I	SLAND, COASTAL HIGH	HAZARD AREA, RIVERINE FLOODWAY		
11 DISTANCE TO WETLANDS	S (5 acre minimum)	12 DISTANCE	TO CRITICAL HABITA	T (of endangered species)		
ESTUARINE	unknown	l i	unknown	(mi)		
A. <1	(mi) B(mi) ENDANG	ERED SPECIES:			
13 LAND USE IN VICINITY	7	 , , , ,				
DISTANCE TO:						
COMMERCIAL/INDUSTR	RESIDENTIAL AREAS; NATI FORESTS, OR WILDLI	ONAL/STATE PAR. FE RESERVES	KS, PRIME	GRICULTURAL LANDS AG LAND AG LAND		
A.<0.1 (mi	B.<1.0	(mi)	c	(mi) D.<1.0 (mi)		
						
•	IN RELATION TO SURROUNDING TOP					
The quarry office, limine works cut back in	ne kilns, and limeplant are locate the river bluffs. The surf	ated on the ea	st bank of the Miss: n fly ash was deposit	issippi River. The underground ited near the crest of the s wouth into the Mississippi		
River. Refer to the	FIT Data Summary report (TDD.#F	-07-8809-008)	for more detail.	, would into the Hississippi		
}						
l t						
·						
VII. SOURCES OF INFOR	MATION (Cite specific reference	s, e.g., state	files, sample analy	ysis, reports)		
Ecology and Environmen	nt, Inc., Field Investigation T	eam (E & E/FIT), June 14, 1989, T	rip Report for the Linwood		
Ecology and Environmen	-07-8809-008. nt, Inc., Field Investigation T	eam (E & E/FIT) May 8, 1989, World	k Plan for the Screening Site		
U.S. Geological Survey Washington, D.C.	nt, Inc., Field Investigation T -07-8809-008. nt, Inc., Field Investigation T mthun Trucking/Linwood Quarry S y, 1970 PR, 7.5 Minute Series T	opographic Map	Andalusia Quadrang	le, Illinois-Iowa,		
"" "" " " " " " " " " " " " " " " " "						

,	PO	TENTIAL HAZARDOUS WASTE SITE	I. IDENTIFICATION			
EPA		01 STATE 02 SITE NUMBER 1A D90852297				
	PART	6 - SAMPLE AND FIELD INFORMATION	D90032297			
II. SAMPLES TAKEN						
SAMPLE TYPE	01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	03 ESTIMATED DATE RESULTS AVAILABLE			
GROUNDWATER	10	Region VII EPA Lab	10/12/89			
SURFACE WATER	5	Region VII EPA Lab	10/12/89			
WASTE kiln ash	7	Region VII EPA Lab	10/12/89			
AIR	0					
RUNOFF	0					
SPILL	0					
SOIL	3	Region VII EPA Lab	10/12/89			
VEGETATION	0		10/12/89			
OTHER sediment	5	Region VII EPA Labe	10/12/89			
III. FIELD MEASUREMEN	TS TAKEN					
01 TYPE	02 COMMENTS					
Conductivity	wells on site sli	ghtly higher than background				
рН	discharge pond in	old quarry has a pH ~9.8				
		,				
IV. PHOTOGRAPHS AND M	APS					
01 TYPE GROUND	AERIAL	02 IN CUSTODY OF				
		(Name of organization or	individual)			
X YES	OCATION OF MAPS					
NO Reg	ion VII EPA Site Ii	les/Ecology and Environment, Inc.				
	OLLECTED (Provide n	arrative description)				
None						
}						
		•				
		c references, e.g., state files, sample anal				
Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), November 1989, Data Summary for the Linword Quarry Site, TDD #F-07-8809-008. Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), June 14, 1989, Trip Report for the Linwood Quarry Site, TDD #F-07-8809-008. Ecology and Environment, Inc., Field Investigation Team (E & E/FIT), May 8, 1989, Work Plan for the Screening Site Inspection of the Umthun Truckin/Linwood Quarry site, TDD #F-07-8809-008.						
1 2222 2339000203, 01	in omenan reaching	22σσα χακείς 52.co, 120 πι σ, σσος σσος				

					Umenun 1	ruck	1119		
		POT	ENTIAL HAZARDOUS	WASTE SITE	I. IDENTII	ICAT	ION		
ЕРА			SITE INSPECTION	REPORT	01 STATE 0	ŞIT	E NUMBER		
		P	ART 7 - OWNER IN	FORMATION	IA I	9085	2297	 .	
II. CURRENT OWNER(S)				PARENT COMPANY (If applica	ble)				
01 NAME Linwood Mining and Minerals	Corp.	02 D	+B NUMBER	08 NAME McCarthy Improvement Co.		09 E	+B NUMBE	R	
03 STREET ADDRESS (P.O. BOX, 401 East Front St.	RFD #, ET	.c.)	04 SIC CODE	10 STREET ADDRESS (P.O. BOX 4321 East 60th	, RFD #, ETC	2.)	11 SIC	CODE	
05 CITY Davenport	06 STATE	07 Z 528	IP CODE	12 CITY Davenport	13 STATE	14 2 528	IP CODE		
01 NAME		02 D	+B NUMBER	08 NAME	<u> </u>	09 [)+B NUMBE	:R	
03 STREET ADDRESS (P.O. BOX,	RFD #, ET	rc.)	04 SIC CODE	10 STREET ADDRESS (P.O. BOX	, RFD #, ET	2.)	11 SIC	CODE	
05 CITY	06 STATE	07 Z	IP CODE	12 CITY	13 STATE	14 2	IP CODE		
01 NAME	<u>- </u>	02 D	+B NUMBER	08 NAME	`	09 D+B NUMBER			
03 STREET ADDRESS (P.O. BOX,	RFD #, E	rc.)	04 SIC CODE	10 STREET ADDRESS (P.O. BOX	, RFD #, ET	.)	11 SIC	CODE	
05 CITY	06 STATE	07 Z	IP CODE	12 CITY	13 STATE	14 2	IP CODE		
III. PREVIOUS OWNER(S) (Lis	t most red	ent	first)	IV. REALTY OWNER(S) (If app	licable; li	st mo	st recen	t firs	
01 NAME 02 D+B NUMBER				01 NAME 02 D+B NUMBER					
03 STREET ADDRESS (P.O. Box,	RFD #, e	tc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, etc	E.)	04 SIC	CODE	
05 CITY	06 STAT	E 07	ZIP CODE	05 CITY	06 STAT	E 07	ZIP CODE	5	
01 NAME		02	D+B NUMBER	01 NAME		02	D+B NUME	3ER	
03 STREET ADDRESS (P.O. Box,	RFD #, e	tc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, et	c.)	04 SIC	CODE	
05 CITY	06 STAT	E 07	ZIP CODE	05 CITY	06 STAT	E 07	ZIP CODE	S	
01 NAME		02	D+B NUMBER	01 NAME -		02	D+B NUMI	BER	
03 STREET ADDRESS (P.O. Box,	RFD #, e	tc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box	:, RFD #, et	c.)	04 SIC	CODE	
05 CITY	06 STAT	E 07	ZIP CODE	05 CITY	06 STAT	E 07	ZIP CODE	£	
				, state files, sample analys					
Personal communication with Ecology and Environment, In Quarry Site, TDD #F-07-88	Gaillard C. Field 09-008.	Krev Inve	ver, Mine Enginne estigation Team (er. E & E/FIT), June 14, 1989, T	rip Report	for	the Linwo	pod	
•									

		POTENTIAL HAZARDOUS	WASTE SITE	I. IDENTIFICATION				
EPA		SITE INSPECTION	REPORT	01 STATE 02 SITE NUMBER IA D90852297				
		PART 8 - OPERATOR II	NFORMATION LA D30032237					
II. CURRENT OPERATOR (Provid	e if diffe	erent from owner)	OPERATOR'S PARENT COMPANY	(If applicable)				
01 NAME Same as owner		02 D+B NUMBER	10 NAME	11 D+B NUMBER				
03 STREET ADDRESS (P.O. BOX,	RFD #, ET	rc.) 04 SIC CODE	12 STREET ADDRESS (P.O. BO)	K, RFD #, ETC.) 13 SIC CODE				
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE 16 ZIP CODE				
08 YEARS OF OPERATION 09	NAME OF OW	wner						
III. PREVIOUS OPERATOR(S) (L	ist most ronly if di	recent first; pro- ifferent from owner)	PREVIOUS OPERATORS' PARENT	COMPANIES (If applicable)				
01 NAME		02 D+B NUMBER	10 NAME	11 D+B NUMBER				
03 STREET ADDRESS (P.O. Box,	RFD #, et	tc.) 04 SIC CODE	12 STREET ADDRESS (P.O. Box	x, RFD #, etc.) 13 SIC CODE				
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE 16 ZIP CODE				
08 YEARS OF OPERATION 09 NAM	E OF OWNER	R DURING THIS PERIOD						
01 NAME		02 D+B NUMBER	10 NAME	11 D+B NUMBER				
03 STREET ADDRESS (P.O. Box,	RFD #, et	tc.) 04 SIC CODE	12 STREET ADDRESS (P.O. Bo	x, RFD #, etc.) 13 SIC CODE				
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE 16 ZIP CODE				
08 YEARS OF OPERATION 09 NAM	E OF OWNER	R DURING THIS PERIOD						
01 NAME		02 D+B NUMBER	10 NAME	11 D+B NUMBER				
03 STREET ADDRESS (P.O. Box,	RFD #, et	tc.) 04 SIC CODE	12 STREET ADDRESS (P.O. Bo	x, RFD #, etc.) 13 SIC CODE				
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE 16 ZIP CODE				
08 YEARS OF OPERATION 09 NAM	E OF OWNER	R DURING THIS PERIOD						
			., state files, sample analy					
Personal communication with Ecology and Environment Inc Quarry Site, TDD #F-07-880	Gaillard E., Field 19-008.	Krewer, Mine Enginee Investigation Team (r. E & E/FIT), June 14, 1989, T	rip Report for the Linwood				

Umthun Trucking

		OTENTI	AL HAZARDOUS	WASTE SITE	I. IDENTI	FICATION
EPA		SIT	E INSPECTION	REPORT	01 STATE 0	2 SITE NUMBER D90852297
	PART 9	- GEN	ERATOR/TRANSI	PORTER INFORMATION	IA	D90632297
II. ON-SITE GENERATOR						
01 NAME	02	D+B N	IUMBER			ļ
Same as owner.						
03 STREET ADDRESS (P.O. BOX,	RFD #, ETC.) 04	SIC CODE			}
05 CITY	06 STATE 0	7 ZIP	CODE			
III. OFF-SITE GENERATOR(S)	L					
01 NAME	0	2 D+B	NUMBER	01 NAME		02 D+B NUMBER
03 STREET ADDRESS (P.O. Box,	RFD #, etc.) 04	SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, et	c.) 04 SIC CODE
05 CITY	06 STATE 0	7 ZIP	CODE	05 CITY	06 STAT	E 07 ZIP CODE
01 NAME	0	2 D+B	NUMBER	01 NAME		02 D+B NUMBER
03 STREET ADDRESS (P.O. Box,	RFD #, etc.) 04	SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, et	CC.) 04 SIC CODE
05 CITY	06 STATE 0	7 ZIP	CODE	05 CITY	06 STAT	TE 07 ZIP CODE
IV. TRANSPORTER(S)			····			
01 NAME	O	2 D+B	NUMBER	01 NAME		02 D+B NUMBER
03 STREET ADDRESS (P.O. Box,	RFD #, etc.) 04	SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, et	cc.) 04 SIC CODE
05 CITY	06 STATE	7 ZIP	CODE	05 CITY	06 STAT	TE 07 ZIP CODE
01 NAME)2 D+B	NUMBER	01 NAME	l	02 D+B NUMBER
03 STREET ADDRESS (P.O. Box,	RFD #, etc.	.) 04	SIC CODE	03 STREET ADDRESS (P.O. Box	, RFD #, et	cc.) 04 SIC CODE
05 CITY	06 STATE	7 ZIP	CODE	05 CITY	06 STAT	TE 07 ZIP CODE
V. SOURCES OF INFORMATION (C	ite specifi	c ref	erences, e.g.	, state files, sample analys	is, reports	<u> </u>
Personal communication with Ecology and Environment, Inc Quarry Site, TDD #F-07~880						

3	POTENTIAL HAZ	ARDOUS WASTE SITE	' L-	I. IDENTIFICATION
EPA '	SITE INSP	ECTION REPORT	[1	01 STATE 02 SITE NUMBER IA D980852297
	PART 10 - PAST RES	PONSE ACTIVITIES	L	
II. PAST RESPONSE ACTIVITIES				
01A. WATER SUPPLY CLOSED			03 AGE	NCY
04 DESCRIPTION	No response activit	ies known at this	time.	
01B. TEMPORARY WATER SUPPLY P	ROVIDED	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01 C. PERMANENT WATER SUPPLY P	ROVIDED	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01 D. SPILLED MATERIAL REMOVED		02 DATE	03 AGE	NCY
04 DESCRIPTION				
01E. CONTAMINATED SOIL REMOVE	D	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01F. WASTE REPACKAGED	······································	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01G. WASTE DISPOSED ELSEWHERE		02 DATE	03 AGE	NCY
04 DESCRIPTION				
01 H. ON SITE BURIAL		02 DATE	03 AGE	NCY
04 DESCRIPTION				,
01 I. IN SITU CHEMICAL TREATME	INT	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01J. IN SITU BIOLOGICAL TREAT	MENT	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01K. IN SITU PHYSICAL TREATME	ENT	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01L. ENCAPSULATION		02 DATE	03 AGE	NCY
04 DESCRIPTION				
01M. EMERGENCY WASTE TREATMEN	NT	02 DATE	03 AGE	NCY
04 DESCRIPTION				
01N. CUTOFF WALLS	02 1	DATE	03 AGE	NCY
04 DESCRIPTION		,		
01O. EMERGENCY DIKING/SURFACE	WATER DIVERSION	02 DATE	03 AGE	NCY
04 DESCRIPTION			_	
01 P. CUTOFF TRENCHES/SUMP		02 DATE	03 AGE	NCY
04 DESCRIPTION				
01 Q. SUBSURFACE CUTOFF WALL		02 DATE	03 AGE	NCY
04 DESCRIPTION				

	POTENTIAL HAZARDOUS WASTE SITE	1. IDENTIFICATION
EPA	SITE INSPECTION REPORT	01 STATE 02 SITE NUMBER 1A D980852297
·	PART 10 - PAST RESPONSE ACTIVITIES	1 33333
II. PAST RESPONSE ACTIVITIES (Cont.		
01R. BARRIER WALLS CONSTRUCTED	02 DATE	03 AGENCY
04 DESCRIPTION	Name .	
01 S. CAPPING/COVERING	02 DATE	03 AGENCY
04 DESCRIPTION		
01 T. BULK TANKAGE REPAIRED	02 DATE	03 AGENCY
04 DESCRIPTION	-	
01U. GROUT CURTAIN CONSTRUCTED	02 DATE	03 AGENCY
04 DESCRIPTION '		
	<u> </u>	
01V. BOTTOM SEALED	02 DATE	03 AGENCY
04 DESCRIPTION	q	
01		02 NORMOV
01W. GAS CONTROL 04 DESCRIPTION	02 DATE	03 AGENCY
04 DESCRIPTION		
01 X. FIRE CONTROL	02 DATE	03 AGENCY
04 DESCRIPTION		
01 Y. LEACHATE TREATMENT	02 DATE	03 AGENCY
04 DESCRIPTION	-	
01Z. AREA EVACUATED	02 DATE	03 AGENCY
04 DESCRIPTION		•
011. ACCESS TO SITE RESTRICTED	02 DATE	O3 AGENCY
04 DESCRIPTION		
01 2. POPULATION RELOCATED	02 DATE	03 AGENCY
04 DESCRIPTION		
01 x 3. OTHER REMEDIAL ACTIVITIES	02 DATE	03 AGENCY
04 DESCRIPTION		
Private well at Umthun Trucking re	cased and grouted to eliminate heavy metal	s contamination and low ph.
	ecific references, e.g., state files, samp	
Ecology and Environment, Inc., Fie	ld Investigation Team (E & E/FIT), Novembe ld Investigation Team (E & E/FIT), June 14 ld Investigation Team (E & E/FIT), May 8 rucking/Linwood Quarry Site, TDD #F-07-880	r 1989, Data Summary for the Linwood
Ecology and Environment, Inc., Fie	ld Investigation Team (E & E/FIT), June 14	, 1989, Trip Report for the Linwood
Ecology and Environment, Inc., Fie Site Inspection of the Umthun T	ld Investigation Team (E & E/FIT), May 8, rucking/Linwood Ouarry Site. TDD #F-07-880	1989, Work Plan for the Screening 9-008.
the checking t		

<u> </u>		Umthun Trucking
	POTENTIAL HAZARDOUS WASTE SITE	I. IDESTIFICATION
ЕРА	SITE INSPECTION REPORT	01 STATE 02 SITE NUMBER D980852297
	PART 11 - ENFORCEMENT INFORMATION	2h 5500052237
II. ENFORCEMENT INFORMATION		
01 PAST REGULATORY/ENFORCEMENT ACTION	YYESNO	
02 DESCRIPTION OF FEDERAL, STATE, LOC	TAL DECULATORY (ENFORCEMENT ACTION	
None known at this time.	REGULATORI / ENFORCEMENT-	
None known at this time.		
		}
		i
		1
	•	
•		
	•	
III SOURCES OF INFORMATION (Cite of	pecific references, e.g., state files, sa	mple analysis, reports)
TIT. BOOKERS OF INFORMATION (CITE S	pecific ferences, e.g., state files, sa	mpre anarysis, reports,
Ecology and Environment, Inc., Field Ouarry Site. TDD #F-07-8809-008.	d Investigation Team (E & E/FIT), Novembe d Investigation Team (E & E/FIT), June 14 d Investigation Team (E & E/FIT), May 8, cking/Linwood Quarry Site, TDD #F-07-8809	, 1989, Trip Report for the Linwood

1A. Cost Center:						2. TDD Number:			
FT 1307	FIT ZONE II CONTRACT Contract Number 68-01-7347 F-07-8809-008								
1B. Account Number:	TECHNICAL DIRECTIVE DOCUMENT (TDD) 2A. Amendment:								
FIA0236SA	*								
3A. Priority: MHigh	3B. Key EPA Contact	:							
☐ Mediur ☐ Low	Name: Pete C	ulver		Phone	e: <u>913</u>	-236-2856			
4A. Estimate of Technical Hours:	4B. Subcontract:	4C. Estimate	of	5A. SSID Numbe	r:	5B. CERID Number:			
· * 578	N/A	N/A		Unassigned		IAD980852297			
5C. EPA Site Name:			5D. City/Cou	nty/State:					
Umthun Trucking			Buffalo/	Scott/Iowa		·			
6. Desired Report Forma		- (Cif)	7A. Activity	Start Date:		stimated Completion			
	Standard Report Other Formal Briefing	r (Specify):	9/26/88	8 · .	_	2/31/89			
8A. Type of Activity:						IT/SCAP Goal: Vill Deliverable Meet			
☐ PA ☐ RCRA-PA ☑ SI ☐ RCRA-SI		nforcement Sur ogram Manager	_	raining eneral Technical		Unit of the Goal?			
ESI		quipment Main		ssistance		X Yes No			
9. General Task Descript	ion: <u>Conduct a site</u>	investigat	tion of Um	thun Trucking	Comp	any in Buffalo.			
Iowa.									
			· · · · · · · · · · · · · · · · · · ·			<u> </u>			
									
	. Perform site re c plan for site inv			ate file revi	l	nterim Deadlines: /30/88			
	ork plan after EPA		' '		力度	renven			
	report within 3 w		ield work.		1512	THE PARTY OF THE P			
	al report & SI form			receipt of		IAY 1 1 1989			
data transmi									
					E	& E K.C.K.			
□ Additional Scope Attached 5) est. 10/31/89 *									
12. Comments: *Amended from 105 to 578 hours to implement field work and prepare final									
report for screening site investigation.									
13. Authorizing:	<i>(10)</i>		1.		14 0)3*a*			
73. Authorizing.									
	(Signature)		—— □PO		3	17/24			
15. Received by:	1 0/	7	Acce	epted	16. D	Pate:			
	Jahr. 1 1	0	Acce	epted with eptions (Attached)		5/12/89			
ICA	Intractor FITOM Signature		—— □ Reie	*	1	0/91			

CHAIN OF CUSTODY RECORD ENVIRONMENTAL PROTECTION AGENCY REGION VII

ACTIVITY LEADER(P	rint)	. 10	NAME (OF SURVEY	OR ACTIVIT	γ, ,			DATE OF COLLECTION 39 SHEET
CONTENTS OF SUID	MENT.	all	um	thur	- Truc	Kiu	<u>-8</u>		DAY MONTH YEAR 1 of 2
CUNTENTS OF SHIPM	CONTENTS OF SHIPMENT TO TYPE OF CONTAINERS SAMPLED MEDIA RECEIVING LABORATORY								
SAMPLE NUMBER	CUBITAINER	SÓ OZI	BOTTLE	BOTTLE	VOA SET (2 VIALS EA)		ment		
NOMBER		ERS OF CONT	AINERS PER SA			water	sedii	dust	other sample numbers, etc.)
DC943001	1	2				X.			
DC94300ZF	- 3					IX.			FIA 0236SA, 24
DC943003	1	2				X			1
DC943004	1	2				X			
DC943005		2				X			
DC943006	_	2				X			
DC943007		2				X			
X9413008		2		•		X			
DC 94300		2				K			
NC943011	1	2				灯	1-		
17943011	1	2				X			
DC943612		2				[]	-		
C943013	1	2				K)	╁		
D C 9 12013	}	2			 	K	╁┈	-	
N GUZNE		2				分	1		
1001930N	1	2				K)	\perp		
D = C(120)	1	2			 	$\frac{1}{\sqrt{1}}$	 		-
066/26/2	1				- 	K)	\vdash	$\vdash \vdash \vdash$	
12 7430111)	2			<u> </u>	₩	╁╴	\vdash	<u> </u>
12 943018	1	2			 	╫	┼	<u> </u>	
DC943019	1	2				17	╁	 	
						╁┼	 		
						+	╁		
						++	╁		
· DECODIDATION OF O	UDMENT.			Т	· ·	LOMEN	<u> </u>	Ш.	
DESCRIPTION OF SH					MODE OF SH	·			
PIECE(S) CO	ONSISTING O	F	BOX(ES)		COMM	ERCIAL	CAR	RIER:	
ICE CHEST((S): OTHER _			— [ER CON	VEYE	ED.	(SHIPPING DOCUMENT NUMBER)
PERSONNEL CUSTO	DY RECORD			d.	,				
RELINQUISHED BY (SAMPLER) DATE TIME RECEIVED BY REASON FOR CHANGE OF CUSTODY									
Janle	flack	5/	25x 131	/	EALED	//// u	VSE4	ALED	Deliver to EPA LAB
RELINQUISHED BY	Alla	DAT	E TIME		EIVED BY	1		, lini	REASON FOR CHANGE OF CUSTODY
Mun	17/4 1	W 1/2	29/201		Zainy			ALED	
SEALED RELINQUISHED BY	UNSEAL	EØ DAT	E TIME	SI REC	ELVED BY	່ ບໍ່	NSE.	ALED	REASON FOR CHANGE OF CUSTODY
	!								- Mariant Committee
SEALED	UNSEAL	EDF	-	Hsi	EALED	U	NSE	ALED	H

CHAIN OF CUSTODY RECORD ENVIRONMENTAL PROTECTION AGENCY REGION VII

ACTIVITY LEADER(F	rint)	ο O .	NAME OF SU	RVEY C	R ACTIVITY	1	, ,			DATE OF COLLECTION SHEET BAY MONTH YEAR Of 1
Meg N			May	1/2/	MITT	W.C	1	t fic		MONTH YEAR 1 1 01
CONTENTS OF SHIP	MENI									
SAMPLE	OUDITATIVE D	04-			VOA SET				other	
NUMBER	CUBITATNER		BOTTLE BOT		(2 VIALS EA)	water	Sedin	dust	V	(condition of samples upon receipt. other sample numbers, etc.)
DC943 0031		3 .			·	П			XX	FIAMORISA 24
00047										1100000
DC 1413 1032		3	 				+	+		
012 943 1033		3				\vdash	$^{+}$	\dagger		
009430034		3				\vdash	+	+	X	
DC943 DO341	4,0	3					+	+	17	
DC9431035		3			,	- ;	4	+-	1	
21943 1036		3				-	4)	4_	ļ	
DK 443 037		3					4	\perp		
DY9431034		3						4		
DC943 0039		3					Ľ	d	Ì	
Dr 943 0040		3					\top		\ \	
149430041		3						1		
rx 9434042		3					L	/		
= 1943 1047							╎	-		,
D (943) D 44		(3.) K				 ,	/	4		
11 1 4 7 4 7 4 7 4 7 4 7 4 7 4 7 4 7 4 7						 	4	+		
				-		\vdash	+	+		
\		_				+	+	+	 	
<u> </u>						-	+	+	ļ. —	
						\vdash	+	+	ļ	
							_	\perp	ļ	
						\sqcup	_	\bot	L	
								\perp		
,										
DESCRIPTION OF SI	HIPMENT			M	ODE OF SHI	PMEN	IT			
PIECE(S) C	ONSISTING OF	- R	OX(ES)		СОММЕ	RCIAL	CAF	RRIEF	R:	
PIECE(S) CONSISTING OF BOX(ES)					COURIE	R				
ICE CHEST(S); OTHER SAMPLER CONVEYED (SHIPPING DOCUMENT NUMBER)							(SHIPPING DOCUMENT NUMBER)			
PERSONNEL CUSTO										
RELINQUISHED BY	(SAMPLER)	DATE	TIME ,	RECEI	VED BY	,	111	14	1	REASON FOR CHANGE OF CUSTODY
Lan	UNSEALE	41 500	/ /300	- A	LED (A)				// _	Delives to FRALAD
RELINQUISHED BY	/ /	DATE	TIME		VED BY/		INSE	ALE	<u>. D T</u>	REASON FOR CHANGE OF CUSTODY
1 9/1.	MON	1 1/2/	[₂ ,]	``	Lower J.		いべ	مريديز ا	 (6 ⁻⁷	1 //
SEALED	UNSEAL		Y/		LED / =	17 > (INS	EALI	ĒD	reason for change of custody
RELINQUISHED BY	<i>'</i>	DATE	TIME	RECE	VED BY					READON FOR CHANGE OF COSTODY
SEALED	UNSEAL	ED		SEA	LED \	ι	JNS	EAL	ED	

E Space



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 25 FUNSTON ROAD KANSAS CITY, KANSAS 66115

DATE:	8/3/89
MEMORANDU	<u>M</u>
SUBJECT:	Data Transmittal for Activity #: DC943 Site Description: Umthun Trucking
FROM:	Andrea Jirka X Chief, Laboratory Branch, ENSV
TO:	Mike Sanderson Chief, Superfund Branch, WSTM
ATTN:	P. Culver

Attached is the data transmittal for the above referenced site. These data have met all quality assurance requirements unless indicated otherwise in the data package. This should be considered a Partial or ____ Complete data transmittal (completes transmittal of ______). If you have any questions or comments, please contact Dee Simmons at 236-3881.

Attachments

cc: Data Files

Ann Melia, E&E/FIT

DATA REPORTING / QUALIFICATION CODES

- U The material was analyzed for, but was not detected. The associated numerical value is the sample detection limit.
- J The associated numerical value is an estimated quantity
 (explanation attached).
- I The data are invalid (compound may or may not be present).
 Resampling and/or reanalysis is necessary for verification.
- N Sample not analyzed.

CODES FOR FLASH POINT DATA

- L The sample did not ignite or "flash". This is the highest temperature at which the sample was tested. It is possible that the material may be ignitable at higher temperatures.
- K The sample did ignite or "flash" at the lowest temperature tested. This is usually the ambient temperature at the time of the test. It is possible that the material may be ignitable at even lower temperatures.

: :	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:	:
	Collected: YR: 89 MO: 5 Day: 23 Time: 1020 Leader: WES MCCALL Sample Number: DC94300 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT WATER, OTHER: Sample Split (circle one): YES NO	
:	Sample Container : Tag Color : Preservative : Analysis Requested	:
	CUBITAINER : HN03/4 C : TOTAL METALS I GAL.AMBER : 4 C : SULFATE 1 GAL.AMBER : 4 C : CHLORIDE Depth: Pan #: Aliquots: R. Parsons R. Parsons	
	COMMENTS OF FIELD PERSONNEL	
: : : : : : : : : : : : : : : : : : : :	Site Description: Background on Moore Creek	

:	Site Name: UMTH Location: BUFF			S	ite Number: Site Code:	:
	,	ber: DC9430 ⊘ ircle one): INSATE, SED	ZF	SMO #:	Leader: WES MCCALL HER:	- : : : : : : : -
	Sample Container CUBITAINER CUBITAINER 1 GAL.AMBER 1 GAL.AMBER	: Tag Color		3/4 C :	Analysis Requested TOTAL METALS DISSUE/ED HETAL SULFATE CHLORIDE	
	Depth: Samplers:	Fan #: 6. Hos R. Pa	js Son	Aliq	uots:,	
	Site Descriptio	COMMENTS OF		Blank		: : : : : : : : : :

: Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code: :				
: Collected: YR: 89 MO: 5 Day: 23 Time: /// Leader: WES MCCALL : Sample Number: DC943003 SMO #: : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: : Sample Split (circle one): YES NO				
: Sample Container : Tag Color : Preservative : Analysis Requested :				
CUBITAINER HN03/4 C TOTAL METALS DISSULVED HETAL AC SULFATE CHLORIDE Depth: 300/ Fan #: Aliquots: Samplers: R. Parsons				
COMMENTS OF FIELD PERSONNEL				
Site Description: Unthur well pH = 7.63 Temp. = 25°C Cond. = 500 µm hos				

. : . :	Site Name: UMTI Location: BUFI					te Number: Bite Code:	: :
		mber: DC9430 6 circle one): RINSATE, SED	# IMENT	SMC	#:	eader: WES MCCALL	:::::::::::::::::::::::::::::::::::::::
:	Sample Containe	r : Tag Color	: Pr	eservative	: 1	Analysis Requested	 :
	CUBITAINER 1 GAL.AMBER 1 GAL.AMBER Depth: Samplers:	R. Pars	on	&	-	TOTAL METALS SULFATE CHLORIDE	
	Site Descripti	COMMENTS OF				djacat King.	

IEM-FC

: Site Name: UMTHUN TRUCKING Site Number: :
: Location: BUFFALO IA Site Code: :
Collected: YR: 89 MO: 5 Day: 23 Time: 1406 Leader: WES MCCALL Sample Number: DC943065 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO
: Sample Container : Tag Color : Preservative : Analysis Requested :
CUBITAINER CONTAINER 1 GAL.AMBER 1 GAL.AM
. COMMENTS OF FIELD PERSONNEL
Site Description: Scott Co. Landfill Well pH = 7.67 Cond. = 500 um hos Temp.= 13°C

	_
: Site Name: UMTHUN TRUCKING Site Number: . : Location: BUFFALO IA Site Code:	:
Collected: YR: 89 MO: 5 Day: 23 Time: 145 Leader: WES MCCALL Sample Number: DC943006 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO	. :
: Sample Container : Tag Color : Preservative : Analysis Requeste	:d :
CUBITAINER : HN03/4 C : TOTAL METALS DESCRIPTION : DISSOLVES METAL 1 GAL.AMBER : 4 C : SULFATE 1 GAL.AMBER : 4 C : CHLORIDE Depth: Fan #: Aliquots: Samplers: R. Paress COMMENTS OF FIELD PERSONNEL	:
Jonaldson Creek (kitween Landfill & Quarry).	:

: Site Name: UMTHUN TRUCKING Site Number Location: BUFFALO IA Site Code	
Collected: YR: 89 MO: 5 Day: 23 Time: 1500 Leader: WE Sample Number: DC943007 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT WATER, OTHER: Sample Split (circle one): YES NO	S MCCALL
: Sample Container : Tag Color : Preservative : Analysis	Requested :
CUBITAINER : HN03/4 C TOTAL ME COSTANDER : 4 C SULFATE 1 GAL.AMBER : 4 C CHLORIDE Depth: Fan #: Aliquots: Samplers: G. Hars COMMENTS OF FIELD PERSONNEL	
Site Description: Back ground on bonaldson Greek	: : : : : : : :

: Site Name: UMTHUN TE : Location: BUFFALO		Site Number: Site Code:	:		
: Collected: YR: 89 N : Sample Number: : Sample Media (circle	DC9430 68	: <u>1700</u> Leader: WES MCCAL SMO #:	 L : :		
: SOIL, DUST, RINSA: : Sample Split (circle:		ER) OTHER:	: : :		
: Sample Container : Ta	ag Color : Preserva	tive : Analysis Request	ed :		
Depth: 300' Samplers: C. R.	: HN03/4 : HN03/4 : 4 C : 4 C : 4 C : 4 C : 4 C	C : TOTAL METALS : SULFATE : CHLORIDE : : : : : : : : Aliquots:			
COM	MENTS OF FIELD PERS	DNNFI			
Site Description: (b) (9)					
cond = 675 Temp = 14	<u> </u>	, 	:		

:	Site Name: UMTHUN TRUCK ING Site Number: : Location: BUFFALO IA Site Code: :					
:	Collected: YR: 89 MO: 5 Day: 24 Time: 0930 Leader: WES MCCALL: Sample Number: DC943069 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO:					
:	Sample Container : Tag Color : Preservative : Analysis Requested : CUBITAINER : : HN03/4 C : TOTAL METALS					
: : : : : : : : : : :	CUBITAINER : HN03/4 C : DISSOLVED METAL ON : 1 GAL.AMBER : 4 C : SULFATE : 1 GAL.AMBER : 4 C : CHLORIDE : 1 GAL.AMBER : 4 C : CHLORIDE : 1 GAL.AMBER : 4 C					
:	Depth: 300' Fan #: Aliquots: Samplers: G. Hays R. Parsons					
	COMMENTS OF FIELD PERSONNEL					
	Site Description: $pH = 7.71$ $cond = 650 \mu h ds$ $1em p = 17^{2} c$					

IBM-FC

: :	Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code: :
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 24 Time: 1070 Leader: WES MCCALL: Sample Number: DC943000 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER OTHER: Sample Split (circle one): YES NO:
	Sample Container: Tag Color: Preservative: Analysis Requested: CUBITAINER: HN03/4 C: TOTAL METALS CUBITAINER: HN03/4 C: DISSOLVED METAL 1 GAL.AMBER: 4 C: SULFATE 1 GAL.AMBER: 4 C: CHLORIDE Depth: Fan #: Aliquots: Samplers: C. Hays R, Parsons
	Smells like Smells like Sulfurs pH = 7.7 complaints of: lime settlement: Cond = 1300 umhos Temp = 15°C

:	Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code: :
	Collected: YR: 89 MO: 5 Day: 23 Time: 09:25 Leader: WES MCCALL Sample Number: DC9430// SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO
	Sample Container : Tag Color : Preservative : Analysis Requested :
	CUBITAINER : HN03/4 C : TOTAL METALS COBITAINER : HN03/4 C : TOTAL METALS 1 GAL.AMBER : 4 C : SULFATE 1 GAL.AMBER : 4 C : CHLORIDE Depth: furface Fan #: Aliquots: Samplers: 100 Million Depth: furface Fan #: Aliquots:
	COMMENTS OF FIELD PERSONNEL
	COMMENTS OF FIELD PERSONNEL Site Description: Linwood Guarry: Confluence of Ponaldson Creek with Minimpi Confluentish = 700 mm/s River. True = 17°C pt = 6.5

: Site Name: UMTHUN TRUCK! : Location: BUFFALO IA	NG Site Number: : Site Code: :
: Collected: YR: 89 MO: Sample Number: DC94 : Sample Media (circle one: SOIL, DUST, RINSATE, : Sample Split (circle one:	SEDIMENT, WATER OTHER:
: Sample Container : Tag Co	olor : Preservative : Analysis Requested :
Depth: Par	HN03/4 C TOTAL METALS HANDS DISSOLVED HE HALE 4 C SULFATE CHLORIDE H: Aliquots: [Vall]2/ner
COMMENTS	OF FIELD PERSONNEL
Site Description: We Linwood Guarry 16 C conductivity 500 m. pH = 6.7	I head at hime polant at

المتراجع والمتراجع
: Site Name: UMTHUN TRUCKING Site Number: : : Location: BUFFALO IA Site Code: :			
: Collected: YR: 89 MO: 5 Day: 23 Time: 10:58 Leader: WES MCCALL : Sample Number: DC943013 SMO #: : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMENT, WATER OTHER: : Sample Split (circle one): YES NO			
: Sample Container : Tag Color : Preservative : Analysis Requested :			
CUBITAINER : HN03/4 C : TOTAL METALS : HN03/4 C : TOTAL METALS : DISSOCYED HETAL : 1 GAL.AMBER : 4 C : SULFATE : 1 GAL.AMBER : 4 C : CHLORIDE : : : : : : : : : : : : : : : : : : :			
COMMENTS OF FIELD PERSONNEL			
Site Description: Well Worth side of Highway 22 Linwood Quarry Temp = 16°C Conductivity - 900 mady pH = 7.3			

: Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code:			
: Collected: YR: 89 MO: 5 Day: 23 Time: //:25 Leader: WES MCCALL Sample Number: DC9430 / SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, DTHER: Sample Split (circle one): YES NO			
: Sample Container : Tag Color : Preservative : Analysis Requested			
CUBITAINER : HN03/4 C : TOTAL METALS FAITHER : HN0			
COMMENTS OF FIELD FERSONNEL			
: Site Description: Well sample at Linwood Guarry office			
Temp = 17 $Condi = 820 \text{ at miles}$ $p/t = 7.1$			

IBM-FC

: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :
: Collected: YR: 89 MD: 05 Day: 2 : Sample Number: DC9430/5 : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMEN : Sample Split (circle one): YES	:
: Sample Container : Tag Color : P	reservative : Analysis Requested :
Depth: Pan #: Samplers: Unh Malacet Depth: Pan #: Depth: Pan #:	HNO3/4 C : TOTAL METALS : HNO3/4 C : DISSULVED HETALE : 4 C : SULFATE , : CHLORIDE : Aliquots:
COMMENTS OF FIE	LD PERSONNEL
Tengo = 19°C	valer under portion of stated, Linkwood Greatry

: Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code:		
: Collected: YR: 89 MO: 5 Day: 23 Time: 410 Leader: WES MCCALL : Sample Number: DC9430 6 SMO #: : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: : Sample Split (circle one): YES NO		
: Sample Container : Tag Color : Preservative : Analysis Requested		
CUBITAINER CHARLER GAL.AMBER GAL.AMBER CHARLER CHARL		
COMMENTS OF FIELD PERSONNEL		
Site Description: Pincharge Pond Linwood Guntry (ord = 1000 uncho Temp = 22°C pH = 9.8		

: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :				
: Collected: YR: 89 MO: 5 Day: 22 : Sample Number: DC943017	SMO #:				
: Sample Split (circle one): YES :					
: Sample Container : Tag Color : Pre	eservative : Analysis Requested :				
: GAL.AMBER : 4	NO3/4 C : TOTAL METALS DISSULTE METAL C : SULFATE C : CHLORIDE Aliquots:				
COMMENTS OF FIELD	COMMENTS OF FIELD PERSONNEL				
Site Description: Alieve ground Conducting = 640 unolig Temp = 12.5°C pH = S.A 6.76	pumped discharge from				

: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :
: Collected: YR: 89 MO: 5 Day: 2 : Sample Number: DC9430/7 Dx: : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMEN : Sample Split (circle one): YES	T, WATER, OTHER:
: Sample Container : Tag Color : P	reservative : Analysis Requested :
Depth: Pan #: Samplers: Web it Almer	HNO3/4 C : TOTAL METALS HNO3/4 C : DISSELLED HETAL 4 C : SULFATE CHLORIDE : : : : : : : : : : : : : : : : : :
COMMENTS OF FIE	_D PERSONNEL
Site Description: Have grow Conductivity = 640 mmchs Temp = 12.56 pH = 6.74	ad pumped discharge from Linwood Quarry

: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :
: Collected: YR: 89 MO: 5 Day: 23 : Sample Number: DC9430 / 5 : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMENT, : Sample Split (circle one): YES :	SMO #:
: Sample Container : Tag Color : Pre	servative : Analysis Requested :
: CODITAINER : M : 1 GAL.AMBER : 4	NO3/4 C TOTAL METALS DESCRIPTION METAL C SULFATE C CHLORIDE Aliquots:
COMMENTS OF FIELD	PERSONNEL
Site Description: (b) (9) (c.d.c.t.v.ty = 640 xcmoly Timp = 14,5° C pH = 6.74	

:	Site Name: UMTHUN TRUCKING Site Number: : Location: BUFFALO IA Site Code: :			
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 23 Time: D4:5 Leader: WES MCCALL Sample Number: DC943019 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO			
:	Sample Container : Tag Color : Preservative : Analysis Requested :			
	CUBITAINER : HN03/4 C : TOTAL METALS : HN03/4 C : DISSOLUED HEFAL : 1 GAL.AMBER : 4 C : SULFATE : 1 GAL.AMBER : 4 C : CHLORIDE : CHL			
	COMMENTS OF FIELD PERSONNEL			
	Site Description: City of Buffield; Well #Z Temp = 14,5°C pH = 120 minhs 6.20 Contactivity = 900 months			

:	Site Name: UMTHUN TRUCKING Location: BUFFALO IA		Site Number: : Site Code: :	
: : : : : : : : : : : : : : : : : : : :	Sample Number: DC94300 Sample Media (circle one): SOIL, DUST, RINSATE, SEI Sample Split (circle one):	O31	Time: 6915 Leader: WES MCCALL SMO #: WATER, OTHER: ASA	
:	Sample Container : Tag Colo	r : Fre	eservative : Analysis Requested :	
	8 OZ.JAR : 8 OZ.JAR : 8 OZ.JAR : 9 OZ.JAR :		: TOTAL METALS : EP TOX : SULFIDE : : : : : : : : : : : : : : : : : : :	
	COMMENTS OF	F FIELD) FERSONNEL	
	Site Description: Pile # \$ 50' from Vent do the South			

: Site Name: UMTHUN T		Site Number: Site Code:
: Collected: YR: 89 : Sample Number: : Sample Media (circl: SOIL, DUST, RINSA: : Sample Split (circl:	DC9430 032 e one): TE, SEDIMENT,	ime: 0936 Leader: WES MCCALL SMO #: WATER: OTHER: ASA
: Sample Container : 1	ag Color : Prese	rvative : Analysis Requested
B QZ.JAR S QZ.JAR S QZ.JAR B QZ.JAR Samplers: G. R.	Pan #: Hays Parsons	: TOTAL METALS : EP TOX : SULFIDE : : : : : : : : : : : : : : : : : : :
CON	MENTS OF FIELD P	ERSONNEL
: Site Description: :	Pile#	2 150' from vent

:	Site Name: UMTHUN TR Location: BUFFALO I		S	ite Number: Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 M Sample Number: Sample Media (circle SOIL, DUST, RINSA) Sample Split (circle	DC9430 633 none): E, SEDIMENT,	SMO #:		: : : : : : :
:	Sample Container : Ta	g Color : Pre	servative :	Analysis Request	ed :
	8 OZ.JAR 8 OZ.JAR 8 OZ.JAR 8 OZ.JAR Depth:		Aliq	TOTAL METALS EF TOX SULFIDE	: : : : : : : : : : : : : : : : : : : :
	COMMENTS OF FIELD PERSONNEL				
: : : : : : : : : : : : : : : : : : : :	Site Description:	Pile #	3 501	SE of Pile	#-2 1#)

:	Site Name: UMTHUN TRUCK <u>I</u> NG	Site Number:
:	Location: BUFFALO IA	Site Code:
:	Collected: YR: 89 MO: 5 Day	23 Time: 0950 Leader: WES MCCALL :
:		<u>.</u>
:	Sample Number: DC9430 63 4	SMO #:
:	Sample Media (circle one):	
:	SOIL, DUST, RINSATE, SEDIME	ENT, WATER, OTHER
:		
:	Sample Split (circle one): Y	ES (NO)
<u>.</u>		:
:	Sample Container : Tag Color :	Preservative : Analysis Requested :
:	8 OZ.JAR : :	: TOTAL METALS :
:	8 OZ.JAR : :	: EP TOX :
:	8 OZ.JAR : :	: SULFIDE :
:	: :	:
	· • • • • • • • • • • • • • • • • • • •	
:		•
:		. :
:	: :	: '
:	:	
:	` :	•
:	Depth: 0-6" Pan #:	Aliquots: 5
:		
:	Samplers: G. Hays	
:	R. Parson	\ S
	COMMENTS OF F	IELD PERSONNEL
:		
:	Site Description:	1.1 - 1 - 6
:	Y, 12 7	14 200'SE & vent
:		
	i ·	:
:		•
:		·
:		:
:		•
:		:

IBM-FC

:	: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :
: : : : : : : : : : : : : : : : : : : :	: Collected: YR: 89 MO: 5 Day: 23 T : Sample Number: DC94300340 : Sample Media (circle one): : SOIL, DUST, RINSATE, SEDIMENT, : Sample Split (circle one): YES	SMO #:
:	: Sample Container : Tag Color : Prese	rvative : Analysis Requested :
	B OZ.JAR B OZ.JAR Depth: O~L Pan #: Samplers: G. Hays R. Parsons	PF TOX SULFIDE Aliquots:
	. COMMENTS OF FIELD F	ERSONNEL
: : : : : : : : : : : : : : : : : : : :		4 200'SE of vent. Implicate

IBM-PC

..

3 3 C

;	Site Name: UMTHUN TRUCKING Location: BUFFALO IA	Site Number: : Site Code: :
: : : : : : : : : : : : : : : : : : : :	Sample Number: DC9430035	SMO #: T. WATER, OTHER:
:	Sample Container : Tag Color : P	reservative : Analysis Requested :
	Depth: O-6 Pan #:	
	COMMENTS OF FIE	LD PERSONNEL
	Site Description: Backgrow	nd NW of vent.

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 23 Time: 1020 Leader: WES MCCALL Sample Number: DC943036 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO	:::::::::::::::::::::::::::::::::::::::
:	Cample Container : Tag Color : Preservative : Analysis Requested	 :
	B OZ.JAR : : : : TOTAL METALS : EP TOX : SULFIDE : : SULFIDE : : : : : : : : : : : : : : : : : : :	
: : : : : : : : : : : : : : : : : : : :	Site Description: Background on Moore Creek	:::::::::::::::::::::::::::::::::::::::

IBM-FC

:	: Site Name: UMTHUN TRUCKING : Location: BUFFALO IA	Site Number: : Site Code: :
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 23 Time: /// Sample Number: DC9430037 SMC Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, Sample Split (circle one): YES NO	:] #: :
:	: Sample Container : Tag Color : Preservative	
	Samplers: G. Haup R. Pausons	TOTAL METALS EP TOX SULFIDE Aliquots: 4
:::::::::::::::::::::::::::::::::::::::	Site Description: Unthun W	ell 50' North

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: S Day: 23 Time: //35 Leader: WES MCCALL Sample Number: DC9430638 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO	- : : : : : : : : : -
:	Sample Container : Tag Color : Preservative : Analysis Requested	:
	8 0Z.JAR : : : : : : : : : : : : : : : : : : :	
	COMMENTS OF FIELD PERSONNEL	
: : : : : : : : : : : : : : : : : : : :	Site Description: Moore Creek bekind Uarthur Tracking	

•	Site Name: UM	THUN TRUCKING		Site Number:	··
:	Location: BU			Site Code:	:
	Sample No	umber: DC9430		14:14 Leader: WES MCCAL WM SMO #:	 .L :
	SOIL, PUST, Sample Split	RINSATE SE		R, OTHER:	:
:	Sample Contain	er : Tag Colo	r : Preservat	ive : Analysis Request	ed :
	8 OZ.JAR 8 OZ.JAR 8 OZ.JAR Depth: O	2 Pan # G.Har R. Par	Some?	: TOTAL METALS : EP TOX : SULFIDE : : : : : : : : : : : : : : : : : : :	: : : : : : : : : : : : : : : : : : : :
		COMMENTS O	F FIELD PERSO	NNEL	
:::::::::::::::::::::::::::::::::::::::	Site Descript	ion: Dor Luck	aldson FU & C	Creek (between 2 varry).	<u>ا</u>

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:
	Collected: YR: 89 MO: 5 Day: 23 Time: 04:50 Leader: WES MCCALL Sample Number: DC9436440 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: 1/4 - 25h / 1/4 /
	Sample Container : Tag Color : Preservative : Analysis Requested
	8 0Z.JAR : : TOTAL METALS 8 0Z.JAR : : EP TOX 8 0Z.JAR : : SULFIDE Depth: 0-3 Pan #: Aliquots: 5 Samplers: Depth : Palmer Ueb Manager
	COMMENTS OF FIELD PERSONNEL
: : : : : : : : : : : : : : : : : : : :	Site Description: Linwied Quarry, Ash particulates from south blower at Kilns.

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:
: : : : : : : : : : : : : : : : : : : :	Sample Number: DC9430 #204 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Fly and line dust Sample Split (circle one): YES NO
:	Sample Container : Tag Color : Preservative : Analysis Requested :
	8 0Z.JAR : : TOTAL METALS 8 0Z.JAR : : EP TOX 8 0Z.JAR : SULFIDE Depth: <u>U-3"</u> Pan #: Aliquots:S Samplers: <u>Nibbic</u> Palmer [Uch /// = Call
	COMMENTS OF FIELD PERSONNEL
	site Description: Course ash and particulates from overflow at "cooling rollers" Linwood Quarry

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 23 Time: 09:30 Leader: WES MCCALL Sample Number: DC9430 \$3042 SMO #: Sample Media (circle one): SOIL, DUST, RINSATE, SEDIMENT, WATER, OTHER: Sample Split (circle one): YES NO	_ ::::::::::
:	Sample Container : Tag Color : Preservative : Analysis Requested	:
	8 0Z.JAR : : : : : : : : : : : : : : : : : : :	
	COMMENTS OF FIELD PERSONNEL	_
: : : : : : : : : : : : : : : : : : : :	Site Description: Linwood Quarry: Confluence of Descalation Creek with Mississ ipport River.	

:	Site Name: UMTHUN TRUCKING Site Number: Location: BUFFALO IA Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Collected: YR: 89 MO: 5 Day: 23 Time: 1500 Leader: WES MCCALL Sample Number: DC9430 0 4 3 SMO #: Sample Media (circle one): WATER, OTHER: Sample Split (circle one): YES NO	
:	Sample Container : Tag Color : Preservative : Analysis Requested	:
	SOZ.JAR : TOTAL METALS SOZ.JAR : EP TOX SULFIDE Depth: 0-21 Pan #: Aliquots: 4 Samplers: 6. Hans L. larsons	
	COMMENTS OF FIELD PERSONNEL	
	Site Description: Background on bonaldson Greek	

IBM-FC

:	Site Name: UMTHUN TRUCK <u>IN</u> G Location: BUFFALO IA	Site Number: Site Code:	:
: : : : : : : : : : : : : : : : : : : :	Sample Number: DC9430 ⊕	IMENT, WATER, OTHER:	-::::::::
:	Sample Container : Tag Color	: Preservative : Analysis Requested	- :
	B QZ.JAR B QZ.JAR B QZ.JAR B QZ.JAR Bepth: Depth: Samplers: Med Med	TOTAL METALS EF TOX SULFIDE Aliquots: Aliquots:	
	COMMENTS OF	FIELD PERSONNEL	_
	Site Description: (b) (C		

ANALYSIS TYPE: METALS, TOTAL

TITLE: UMTHUM TRUCKING

MATRIX: WATER

LAB: NANCO

CYANIDE

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55

METHOD: 9001W71

UNITS: UG/L CASE: 12127

DATE: 07/20/89

SAMPLES	DC943001	DC943002F	DC943003	DC943004
ALUMINUM +	200 U	72 J	200 U	200 U
ANTIMONY	,60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM	33 J	200 U	89 J	50 J
BERYLLIUM	5.0 U	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	170000	5000 U	77000	170000
CHROMIUM	12	10 U	28	10 U
COBALT	50 U	50 U	50 U	50 Ŭ
COPPER	25 U	25 U	13 J	25 U
IRON	410 U	100	160 U	170 U
LEAD	5.0 U	0.40 J	5.0 U	5.0 U
MAGNESIUM	45000	5000 U	31000	46000
MANGANESE	210	15 U	4.0 J	52
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	40 U	8.0 J	40 U
POTASSIUM	5500	5000 U	1700 J	7500
SELENIUM	5.0 U	5.0 U	5.0 U	5.0 U
SILVER	10 U	10 U	10 U	10 U
SODIUM	16000	5000 U	14000	15000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 U	50 U
ZINC	25 U	18 J	160	25 U

N

UNITS: UG/L CASE: 12127 TITLE: UMTHUM TRUCKING MATRIX: WATER METHOD: 9001W71 LAB: NANCO

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55 DATE: 07/20/89

SAMPLES	DC943005	DC943006	DC943007	DC943008
ALUMINUM *	200 U	200 U	200 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM	110 Ј	74 J	63 J	98 J
BERYLLIUM	5.0 U	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	88000	15000 0	130000	77000
CHROMIUM	. 10 U	9.0 J	10 U	10 U
COBALT	50 U	50 U	50 U	50 U
COPPER	25 U	25 U	25 U	25 U
IRON	1800	520	340 U	1900
LEAD	6.1 U	5.0 U	`5.0 U	5.0 U
MAGNESIUM	34000	47000	42000	33000
MANGANESE 5	10 Ј	210	250	26
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	11 J	40 U	40 U
POTASSIUM	1600 J	4000 J	3300 J	7300
SELENIUM	5.0 U	5.0 U	5.0 U	5.0 U
SILVER	10 U	10 U	10 U	10 U
SODIUM	19000	24000	28000	48000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 Ū	50 U
ZINC	800	35 U	33 U	800
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING

MATRIX: WATER METHOD: 9001W71 UNITS: UG/L CASE: 12127

LAB: NANCO

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER:

DATE: 07/20/89

KEATEM	TEAET:	2	DA	A'I'A	FILE	:	P55

SAMPLES	DC943009	DC943010	DC943011	DC943012
ALUMINUM :	200 U	200 U	310 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM	100 J	62 J	54 J	61 J
BERYLLIUM	. 5.0 U	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	90 00	15000 0	110000	74000
CHROMIUM	10 U	9.0 J	28	10 U
COBALT	50 U	50 U	50 U	50 U
COPPER	25 U	20 J	25 U	25 U
IRON	190 U	100 U	500 U	120 U
LEAD	5.0 U	5.3 U	5.0 U	5.0 U
MAGNESIUM	33000	560 00	19000	29000
MANGANESE	12 J	49	71	11 J
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	22 J	40 U	40 U
POTASSIUM	1800 J	3200 J	11000	3000 J
SELENIUM	5.0 U	5.0 U	5.0 'U	5.0 U
SILVER	10 U	10 U	10 U	10 U
SODIUM	16000	76000	35000	35000 ·
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 U	50 U
ZINC	510	1600	20 U	50 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING

LAB: NANCO

SAMPLE PREP:

ANALYST/ENTRY: PLC REVIEWER:

OCCUR

MATRIX: WATER

UNITS: UG/L

CASE: 12127

DATE: 07/20/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55

SAMPLES	DC943	3013	DC94:	3014 ⁻	DC94:	3015	DC943	3016
ALUMINUM	200	U	200	U	200	U	490	U
ANTIMONY	60	U	60	U	60	U	60	U
ARSENIC	. 10	Ü	10	U	10	U	10	U
BARIUM	24	J	43	J	40	J	34	J .
BERYLLIUM	5.0	U	2.0	J	5.0	U	5.0	U
CADMIUM		U	5.0	U	5.0	U	5.0	U
CALCIUM	53000		110000		91000		240000	
CHROMIUM	10	U		U	10	U	16	
COBALT	50	U	11	J	50	U	50	U
COPPER	18	J	12	J	25	U	10	J
IRON	100	U	24000	·	140	U	610	
LEAD	5.0	U	8.6		5.0	U	5.1	U
MAGNESIUM	19000		29000		36000		3100	J
MANGANESE	52		150		5.0	J	43	
MERCURY	0.20	U	0.20	U	0.20	U	0.20	U
NICKEL	40	U	71		19	J	· 14	J
POTASSIUM	5000	J	1700	J	7900		17000	
SELENIUM	25	U	5.0	U	5.0	U	5.0	U
SILVER	10	U	10	U	10	U	10	U
SODIUM	180000		81000		12000		51000	
THALLIUM	10	U	10	U	10	U	10	U
VANADIUM'	50	U	50	U	50	U	50	U
ZINC	540		1100		27	U	20	U
CYANIDE		N		N		N		N

UNITS: UG/L CASE: 12127 DATE: 07/20/89 TITLE: UMTHUM TRUCKING MATRIX: WATER METHOD: 9001W71 LAB: NANCO

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55

SAMPLES	DC943	3017	DC943	3017D	DC943	3018	DC94:	3019	
ALUMINUM =	200	U	200	U	200	U	200	U	
YNOMITNA	60	U	60	บ	60	U	60	U	
ARSENIC	10	U	10	U	10	U	10	U	
BARIUM	79	J	81	J	48	J	120	J	
BERYLLIUM	5.0	U	5.0	U	5.0	U	5.0	U	
CADMIUM	5.0	U	5.0	U	5.0	U	5.0	U	
CALCIUM	80000		78000		160000		85000		
CHROMIUM	10	U	16		10	U	. 10	U	
COBALT	50	U	50	U	50	U	50	U	
COPPER	25	U	25	U	11	J	. 25	U	
IRON	130	U	190	U	1000		1900		
LEAD	5.0	U	5.0	U	5.0	U	5.0	U	
MAGNESIUM	35000		35000		40000		33000		
MANGANESE	5.0	J	5.0	J	28		21		
MERCURY	0.20	U	0.20	U	0.20	U	0.20	U	
NICKEL	9.0	J	16	J	13	J	40	U	
POTASSIUM	2900	J	2400	J	1900	J	1600	J	
SELENIUM	5.0	U	5.0	U	5.0	U	5.0	U	
SILVER	10	U	10	U	10	U	10	U	
SODIUM	18000		17000		20000		12000		
THALLIUM	10	U	10	U	10	U	10	U	
VANADIUM	50		50	U	50	U	50	U	
ZINC	20		28	Ū	20	U	1500		
CYANIDE		N		N		N		N	

TITLE: UMTHUM TRUCKING

LAB: NANCO

METHOD: 9001W71

SAMPLE PREP:

ANALYST/ENTRY: PLC REVIEWER:

OCC DATE: 07/21/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

SAMPLES	DC943031	DC943032	DC943033	DC943034
ALUMINUM =	7300	6600	6600	6500
ANTIMONY	18 U	16 U	16 U	16 U
ARSENIC	5.9 J	5.0 J	4.9 J	5.0 J
BARIUM	53 J	49 J	36 J	52 J .
BERYLLIUM	1.8	1.9	2.2	2.1
CADMIUM	0.60 J	0.53 J	0.81 J	1.3 U
CALCIUM	310000 J	320000 J	250000 J	300000 J
CHROMIUM	15	12	, 12	11
COBALT	6.6 J	4.5 J	4.0 J	3.9 J
COPPER	38 J	4.8 J	2.2 J	3.4 J
IRON	13000	1500 0	14000	13000
LEAD	12	. 10	7.4	6.1
MAGNESIUM	2400	2400	1000 J	1300 J
MANGANESE ,	520 J.	590 J	450 J	500 J
MERCURY	0.15 U	0.13 U	0.13 U	0.13 U
NICKEL	13	15	13	14
POTASSIUM	1500 U	1800 U	2200 U	1500 U
SELENIUM	0.69 J	0.75 J	0.65 J	0.62 J
SILVER	6.0	5.1	4.3	5.2
SODIUM	1500 U	1300 U	1300 U	1300 U
THALLIUM	0.30 J	0.37 J	0.24 J	0.23 J
VANADIUM	23 U	22 U	24 U	24 U
ZINC	96	56 U	110	75 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING MATRIX: SEDIMENT UNITS: MG/KG LAB: NANCO METHOD: 9001W71 CASE: 12127

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56 DATE: 07/21/89

SAMPLES	DC943034D	DC943035	DC943036	DC943037
ALUMINUM	7700	16000	4000	10000
ANTIMONY	18 J	35 J	35 J	13 J
ARSENIC	5.4 J	9.6 J	4.1 J	5.0 J
BARIUM	57	140	160	110
BERYLLIUM	2.4	1.9	2.9	1.4
CADMIUM	0.48 J	1.2 U	0.87 J	0.45 J
CALCIUM	3400 00 J	5300 J	5600 J	38000 J
CHROMIUM	12	21	8.7	16
COBALT	4.3 J	11 J	28	6.8 J
COPPER	5.3 J	6.0 U	7.3 U	5.7 U
IRON	15000	23000	37000	15000
LEAD	6.3	18	6.5	14
MAGNESIUM	1400	2800	950 J	2500
MANGANESE	540 J	610 J	2200 J	790 J
MERCURY	0.12 U	0.12 U	0.14 U	0.11 U
NICKEL	14	22	64	16
POTASSIUM	1700 บ	2100 U	1500 U	1900 U
SELENIUM	0.60 J	0.41 J	0.23 J	0.41 J
SILVER	5.3	2.4 U	2.9 U	2.3 U
SODIUM	1200 U	1200 U	1500 U	1100 U
THALLIUM	0.19 J	0.19 J	2.9 U	0.18 J
VANADIUM	28 U	39 U	21 U	28 U
ZINC	180	110	160	76 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING

MATRIX: SEDIMENT METHOD: 9001W71

LAB: NANCO

UNITS: MG/KG CASE: 12127

CYANIDE

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

DATE: 07/21/89

SAMPLES	DC943	038 DC94	3039 DC94	3040	DC943	3041
ALUMINUM :	12000	8500	4300)	3400	
ANTIMONY	23	J 25	J 12	U	14	J
ARSENIC	6.1	J 5.9	J 3.6	J	3.2	J
BARIUM	100	86	67	7	68	
BERYLLIUM	1.1	J 1.6	0.82	: J	0.80	J
CADMIUM	1.1	J 0.53	J 1.0	U	1.0	U
CALCIUM	200000	J 22000	J 310000) J :	390000	J
CHROMIUM	18	16	6.8	}	6.8	
COBALT	8.5	J 7.7	J 10	U	1.8	J
COPPER	9.2	Ü 6.6	U 14	J	14	J
IRON	12000	17000	7900)	6900	
LEAD	79	9.5	13	}	8.1	
MAGNESIUM	7800	7000	19000)	9800	
MANGANESE	2000	J 730	J 430	J	420	J
MERCURY	0.18	U 0.13	U 0.10	U	0.10	U
NICKEL	22	19	` 77	,	66	
POTASSIUM	4400	U 1300	U 1300	U	1000	U
SELENIUM	1.8	U 0.40	J 1.0	U	0.38	J
SILVER	5.5	2.6	U 2.9)	4.0	
SODIUM	280	J 1300	U 1000	U	1000	U
THALLIUM	2.1	J 2.6	U 0.18	J	2.0	U
VANADIUM	32	บ 25	U 210)	190	
ZINC	120	69	U 43	U	68	U

MATRIX: SEDIMENT UNITS: MG/KG TITLE: UMTHUM TRUCKING CASE: 12127 DATE: 07/21/89 LAB: NANCO METHOD: 9001W71 ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

SAMPLE PREP: REVIEW LEVEL: 2

DC943042	DC943043	DC943044
6700	4700	10000
18 U	16 U	15 J
4.3 J	3.7 J	5.3 J
79	75	270
1.2 J	1.1 J	1.4
1.5 U	1.4 U	0.48 J
1600 00 J	8000 J	3400 J
11	7.9	15
3.2 J	6.0 J	11 J
7.3 U	6.8 U	6.0 U
11000	12000	14000
9.4	9.4	24
6500	1500	1800
420 J	420 J	2100 J
0.15 U	0.14 U	0.12 U
13	12	23
1500 บ	1400 U	2300 ,U
0.44 J	0.38 J	0.41 J
2.9 U	2.7 U	2.4 U
1500 U	1400 U	1200 U
2.9 U	2.7 U	0.22 J
21 U	16 U	27 U
63 U	130	110
N	N	N
	6700 18 U 4.3 J 79 1.2 J 1.5 U 160000 J 11 3.2 J 7.3 U 11000 9.4 6500 420 J 0.15 U 13 1500 U 0.44 J 2.9 U 1500 U 2.9 U 21 U 63 U	6700 4700 18 U 16 U 4.3 J 3.7 J 79 75 1.2 J 1.1 J 1.5 U 1.4 U 160000 J 8000 J 11 7.9 3.2 J 6.0 J 7.3 U 6.8 U 11000 12000 9.4 9.4 6500 1500 420 J 420 J 0.15 U 0.14 U 13 12 1500 U 1400 U 0.44 J 0.38 J 2.9 U 2.7 U 1500 U 1400 U 2.9 U 2.7 U 21 U 16 U 63 U 130



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT Q.

THRU:

Joseph Chandler, TATL

DATE:

, July 20, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-QSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 12127

CONTRACT NO.: 68-W8-0060

SITE: UMTHUM TRUCKING

REVIEWER: P. COX

LABORATORY: NANCO

METHOD NO.: 9001W71

EPA ACTIVITY: DC943

MATRIX: WATER

SMO SAMPLE NOS.		NOS.	EPA SAMPLE NOS.	MPLE NOS.		
	MGF169	MGE207	DC943001	DC943011		
	MGF170	MGE208	DC943002F	DC943012		
	MGF171	MGE209	DC943003	DC943013		
	MGF172	MGE210	DC943004	DC943014		
	MGE201	MGE211	DC943005	DC943015		
	MGE202	MGE212	DC943006	DC943016		
	MGE203	MGE213	DC943007	DC943017		
	MGE204	MGE214	DC943008	DC943017D		
	MGE205	MGE215	DC943009	DC943018		
	MGE206	MGE216	DC943010	DC943019		

GENERAL

Case 12127 contained 20 water samples analyzed for total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (T1) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

Technical holding times and required preservation were met on all samples, with the exception of mercury (Hg) preparation/analysis holding times which were exceeded by 6 days. All data was qualified by the holding time/preservation rules.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Arsenic (As), vanadium (V), and zinc (Zn) were reported in the continuing calibration blanks and aluminum (Al) and lead (Pb) in the preparation blank. Field blank DC943002F (MGF170) was analyzed with aluminum (Al), iron (Fe), lead (Pb), and zinc (Zn) reported. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except antimony (Sb) and potasium (K) which were detected but not an elements in the EPA ICS solution. Antimony was reported at levels less than the instrument detection limit (IDL) and potassium at levels greater than the instrument detection limit (IDL). All data was qualified for potassium (K) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements.

SPIKES

All analytes were within limit requirements for percent recovery except antimony (Sb), selenium (Se), and thallium (Tl). All data was qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirments. Various samples for arsenic (As), selenium (Se), and thallium (Tl) were qualified due to post digestion spike recoveries being outside quality control limits.

ICP SERIAL DILUTION

Aluminum (Al), iron (Fe), potassium (K), and zinc (Zn) were exceptions to the ICP rule for percent difference since the original sample concentration was less than 50 times the instument detection limit (IDL). No data was qualified by the ICP serial dilution rules.

PERFORMANCE EVALUTATION SAMPLE

No performance evaluation sample was submitted to the laboratory for analysis.



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT &

THRU:

Joseph Chandler, TATIS

DATE:

July 21, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-QSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 12127

CONTRACT NO.: 68-W8-0060

SITE: UMTHUM TRUCKING

REVIEWER: P. COX

LABORATORY: NANCO

EPA SAMPLE NOS.

METHOD NO.: 9001W71 EPA ACTIVITY: DC943

MATRIX: WATER/ASH/SOIL

SMO	SAMPLE	NOS.	

MGE217	MGE225	DC943900P	DC943037
MGE218	MGE226	DC943031	DC943038
MGE219	MGE227	DC943032	DC943039
MGE220	MGE228	DC943033	DC943040
MGE221	MGE229	DC943034	DC943041
MGE222	MGE230	DC943034D	DC943042
MGE223	MGE231	DC943035	DC943043
MGE224	MGE232	DC943036	DC943044

GENERAL

Case 12127 contained 16 water/ash/soil samples analyzed for total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (TI) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

No technical holding times or required preservation are specified for soil samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Arsenic (As) was reported in the water matrix initial calibration blank and aluminum (Al), iron (Fe), potassium (K), vanadium (V), and zinc (Zn) in the continuing calibration blanks. Chromium (Cr) was reported in the water matrix preparation blank. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except antimony (Sb) and potasium (K) which were detected but not an elements in the EPA ICS solution. Antimony was reported at levels greater than the instrument detection limit (IDL) and potassium at levels less than the instrument detection limit (IDL). All data was qualified for antimony (Sb) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements except calcium in the soil matrix sample. All soil matrix samples were qualified by the duplicate rules.

SPIKES

All analytes were within limit requirements for percent recovery except antimony (Sb), arsenic (As), copper (Cu), manganese (Mn), selenium (Se), and thallium (Tl) in the soil matrix sample and lead (Pb) and silver (Ag) in the water matrix sample. Associated sample data was qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirments. Various samples for selenium (Se) and thallium (T1) were qualified due to post digestion spike recoveries being outside quality control limits.

ICP SERIAL DILUTION

Barium (Ba), beryllium (Be), calcium (Ca), magnesium (Mg), and vanadium (V) in the soil matrix sample and cadmium (Cd) and nickel (Ni) in the water matrix sample were exceptions to the ICP rule for percent difference since the original sample concentration was less than 50 times the instument detection limit (IDL). No data was qualified by the ICP serial dilution rules.

PERFORMANCE EVALUTATION SAMPLE

Performance evaluation sample DC943900P (MGE217) was analyzed with all analytes present in the audit being identified. Calcium (Ca) and sodium (Na) were also reported. No data was qualified by the performance evaluation sample.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 25 FUNSTON ROAD KANSAS CITY, KANSAS 66115

Date:	8/18/89			
MEMORANDUI	<u>1</u>			
SUBJECT:	Data Transmittal for Activity #: DC943, Site Description: Unthun Trucking			
FROM:	Andrea Jirka X Chief, Laboratory Branch, ENSV			
TO:	P. Culver SPFD-WSTM			
Atta	ched is the data transmittal for the above referenced			
site. The	ese data have met all quality assurance requirements			
unless in	dicated otherwise in the data package. This is a Modi-			
fied Data	Transmittal; these data are modified and differ from			
data prev	iously transmitted. If you have any questions or com-			
ments, ple	ease contact Dee Simmons at 236-3881.			
Attachmen	t			
	File Melia, E3E/FIT			
MODIFIED DATA: Data were modified for the following reason(s):				

DATA REPORTING / QUALIFICATION CODES

- U The material was analyzed for, but was not detected. The associated numerical value is the sample detection limit.
- J The associated numerical value is an estimated quantity (explanation attached).
- I The data are invalid (compound may or may not be present). Resampling and/or reanalysis is necessary for verification.
- N Sample not analyzed.

CODES FOR FLASH POINT DATA

- L The sample did not ignite or "flash". This is the highest temperature at which the sample was tested. It is possible that the material may be ignitable at higher temperatures.
- K The sample did ignite or "flash" at the lowest temperature tested. This is usually the ambient temperature at the time of the test. It is possible that the material may be ignitable at even lower temperatures.

UNITS: MG/KG CASE: 12127 TITLE: UMTHUM TRUCKING MATRIX: SEDIMENT METHOD: 9001W71 LAB: NANCO DATE: 08/17/89

N

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

SAMPLES	DC943038	DC943040
ALUMINUM	12000	4300
ANTIMONY	23 Ј	12 U
ARSENIC	6.1 J	3.6 J
BARIUM	100	67
BERYLLIUM	1.1 J	0.82 J
CADMIUM	1.1 J	1.0 U
CALCIUM	200000 J	310000 J
CHROMIUM	18	6.8
COBALT	8.5 J	10 U
COPPER	9.2 U	14 J
IRON	12000	7900
LEAD	79	13
MAGNESIUM	7800	19000
MANGANESE	2000 J	430 J
MERCURY	0.18 U	0.10 U
NICKEL	22	77 ·
POTASSIUM	4400 U	1300 U
SELENIUM	4.5 J	1.4 J
SILVER	5.5	2.9
SODIUM	280 J	1000 U
THALLIUM	2.1 J	0.18 J
VANADIUM	32 U	210
ZINC	120	43 U

CYANIDE



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment-

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT ?

DATE:

August 17, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-OSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

NANCO

CASE NO.: 12127 LABORATORY: CONTRACT NO.: 68-W8-0060 METHOD NO.: 9001W71 SITE: UMTHUM TRUCKING EPA ACTIVITY: DC943 REVIEWER: P. COX MATRIX: WATER/ASH/SOIL

SMO SAMPLE NOS. EPA SAMPLE NOS. MGE217 DC943037 MGE225 DC943900P MGE218 MGE226 DC943031 DC943038 MGE219 MGE227 DC943032 DC943039 MGE220 MGE228 DC943040 DC943033 MGE221 MGE229 DC943034 DC943041 MGE222 MGE230 DC943034D DC943042 MGE223 MGE231 DC943043 DC943035 MGE224 MGE232 DC943036 DC943044

Resubmittal of data due to laboratory response to results of contract compliance screening (CCS) resulted in one change to the memo and two changes to selenium (Se) results in samples DC943038 and DC943040 on the data sheets. Corrected memo and data sheets are being submitted and are attached.

recycled paper

GENERAL

Case 12127 contained 16 water/ash/soil samples analyzed for total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (Tl) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

No technical holding times or required preservation are specified for soil samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Arsenic (As) was reported in the water matrix initial calibration blank and aluminum (Al), iron (Fe), potassium (K), vanadium (V), and zinc (Zn) in the continuing calibration blanks. Chromium (Cr) was reported in the water matrix preparation blank. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except antimony (Sb) and potasium (K) which were detected but not an elements in the EPA ICS solution. Antimony was reported at levels greater than the instrument detection limit (IDL) and potassium at levels less than the instrument detection limit (IDL). All data was qualified for antimony (Sb) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements except calcium in the soil matrix sample. All soil matrix samples were qualified by the duplicate rules.

SPIKES

All analytes were within limit requirements for percent recovery except antimony (Sb), arsenic (As), copper (Cu), manganese (Mn), selenium (Se), and thallium (Tl) in the soil matrix sample and lead (Pb) and silver (Ag) in the water matrix sample. Associated sample data was qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirments. Various samples for selenium (Se) and thallium (Tl) were qualified due to post digestion spike recoveries being outside quality control limits.

ICP SERIAL DILUTION

Barium (Ba), beryllium (Be), magnesium (Mg), and vanadium (V) in the soil matrix sample and cadmium (Cd) and nickel (Ni) in the water matrix sample were exceptions to the ICP rule for percent difference since the original sample concentration was less than 50 times the instument detection limit (IDL). No data was qualified by the ICP serial dilution rules.

PERFORMANCE EVALUTATION SAMPLE

Performance evaluation sample DC943900P (MGE217) was analyzed with all anlytes present in the audit being identified. Calcium (Ca) and sodium (Na) were also reported. No data was qualified by the performance evaluation sample.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 25 FUNSTON ROAD KANSAS CITY, KANSAS 66115

DATE: 8/18/89

MEMORANDUM

SUBJECT: Data Transmittal for Activity #:

Site Description:

FROM:

Andrea Jirka X

Chief, Laboratory Branch, ENSV

TO:

Mike Sanderson

Chief, Superfund Branch, WSTM

ATTN:

Attached is the data transmittal for the above referenced site. These data have met all quality assurance requirements unless indicated otherwise in the data package. This should be considered a ____ Partial or ___ Complete data transmittal (completes transmittal of ____ 8/3/89___). If you have any questions Modified Data___ 8/17/89__ or comments, please contact Dee Simmons at 236-3881.

Attachments

cc: Data Files

Ann Melia, E&E/FIT

DATA REPORTING / QUALIFICATION CODES

- U The material was analyzed for, but was not detected. The associated numerical value is the sample detection limit.
- J The associated numerical value is an estimated quantity
 (explanation attached).
- I The data are invalid (compound may or may not be present).
 Resampling and/or reanalysis is necessary for verification.
- N Sample not analyzed.

CODES FOR FLASH POINT DATA

- L The sample did not ignite or "flash". This is the highest temperature at which the sample was tested. It is possible that the material may be ignitable at higher temperatures.
- K The sample did ignite or "flash" at the lowest temperature tested. This is usually the ambient temperature at the time of the test. It is possible that the material may be ignitable at even lower temperatures.

TITLE: UMTHUM TRUCKING

MATRIX: WATER METHOD: 9001W71

LAB: SILVER VALLEY

CASE: 4740G DATE: 08/15/89

10 U

2600 J

0.90 J

12 J

6.3 J

N

.

UNITS: UG/L

SILVER

SODIUM

ZINC

CYANIDE

THALLIUM

VANADIUM

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P07 DATA FILE : PO7

10 U

2600 J

1.6 J

8.9 J

20 U

N

10 U

1.1 J

10 J

8.8 J

N

3300 J

SAMPLES	DC943031	DC943032	DC943033	DC943034
ALUMINUM	210	200 U	200 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	√3.0 J	2.5 J	10 U
BARIUM	130 Ј	130 J	43 J	120 J
BERYLLIUM	5.0 U	5.0 U	5.0 U	- 5.0 บ
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	1700000	2100 J	2000000	2000000
CHROMIUM	10 U	10 U	10 U	10 U
COBALT	50 U	50 U	50 U	50 U
COPPER	25 U	25 U	25 U	25 U
IRON	11 J	100 U	27 J	100 U
LEAD	, 5.0 U	5.0 U	5.0 U	5.0 U
MAGNESIUM	4600 J	15000	7500	7300
MANGANESE	15 U	1200	940	1500
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	40 U	40 U	40 U
POTASSIUM	4600 J	25000	36000	23000
SELENIUM	50 U	50 U	50 U	50 U

10 U

10 U

20 U

N

900 J

8.0 J

MATRIX: WATER
METHOD: 9001W71
SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P07

UNITS: UG/L CASE: 4740G

DATE: 08/15/89

SAMPLES	DC943034D	DC943035	DC943036	DC943037
LUMINUM	200 U	200 U	200 U	120 J
NTIMONY	60 U	60 U	60 U	60 U

ALUMINUM	200	TT	200	IJ	200	U	120	J	
ANTIMONY		Ū	60	Ŭ	60	U		U	
ARSENIC	4.4	J	10	Ŭ	10	Ū		Ū	
BARIUM	160	J	240	•	440	_	760	_	
BERYLLIUM	5.0	_	5.0	U	5.0	U	5.0	U	
CADMIUM	5.0		5.0	Ū	5.0	U	5.0		
CALCIUM	2000000	•	53000	•	150000		1200000		
CHROMIUM		U	10	U	10	U	10	U	
COBALT	50	Ū	50		50	U	50	U	
COPPER		Ū	25	U	25	U	25	U	
IRON	100	Ū	18	J	120		100	U	
LEAD	,	Ū	5.0	U	5.0	U	5.0	U	
MAGNESIUM	7100		4300		9000		25000		
MANGANESE	1500		130		8000		4300		
MERCURY	0.20	U	0.20	U	0.20	U	0.20	U	
NICKEL		U			40	U	40	U	
POTASSIUM	23000		10000		5000	U	12000		·
SELENIUM	50	U	5.0	U	5.0	Ű	50	U	
SILVER	10	U	10	U	10	U	10	U	
SODIUM	2600	J	320	J	580	J	790	J	
THALLIUM	0.90	J	10	U	1.0	J	1.2	J	
VANADIUM	12	J	50	U	50	U.	4.1	J	
ZINC	6.6	J	20	U	23		. 30		
CYANIDE		N		N		N		N	

TITLE: UMTHUM TRUCKING MATRIX: WATER UNITS: UG/L METHOD: 9001W71 CASE: 4740G LAB: SILVER VALLEY

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P07 DATE: 08/15/89

SAMPLES	DC943038	DC943039	DC943040	DC943041
ALUMINUM	88 J	200 U	200 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM -	260 [°]	550	220	670
BERYLLIUM	5.0 U	0.90 J	5.0 U	5.0 U
CADMIUM	5.0 U	3.4 J	5.0 U	5.0 U
CALCIUM	2000000	480000	2900000	2700000
CHROMIUM	10 U	10 U	10 U	10 U
COBALT	50 U	50 U	50 U	50 U
COPPER	25 U	25 U	25 U	25 U
IRON	14 J	29 J	100 U	100 U
LEAD	5.0 U	5.0 U	50 U	50 U
MAGNESIUM	53000	120000	140 J	5000 U
MANGANESE	13000	5900	2.4 J	15 U
MERCURY	0.20 U	0.20 U	0.20 U	0.40
NICKEL	51	44	40 U	40 U
POTASSIUM	33000	5000 U	8700	3300 J
SELENIUM	50 U	5.0 U	50 U	50 U
SILVER	10 U	10 U	10 U	1 0 U
SODIUM	2800 J	690 J	1700 J	790 J
THALLIUM	3.9 J	1.0 J	1.4 J	10 U
VANADIUM	16 J	50 U	14 J	4.4 J
ZINC	20 U	7.4 J	20 U	20 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING

MATRIX: WATER

LAB: SILVER VALLEY

METHOD: 9001W71

UNITS: UG/L CASE: 4740G DATE: 08/15/89,

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE : P07

SAMPLES	DC943042	DC943043	DC943044
ALUMINUM	200 U	200 U	200 U
ANTIMONY	60 U	27 J	60 U
ARSENIC	2.3 J	2.8 J	10 U
BARIUM	810	760	460
BERYLLIUM	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	. 5.0 U
CALCIUM	18000 0	210000	35000
CHROMIUM	10 U	10 U	10 🛈
COBALT	29 J	62	50 U
COPPER	. 25 U	25 U	25 U
IRON	37 J	420	110
LEAD	5.0 U	5.0 U	5.0 U
MAGNESIUM	18000	23000	3500 J
MANGANESE	6600	13000	1400
MERCURY	0.20 U	0.20 U	0.20 U
NICKEL	54	47	40 U
POTASSIUM	5000 U	5000 U	8700
SELENIUM	50 U	5.0 U	5.0 U
SILVER	10 U	10 U	10 U
SODIUM	1200 J	1200 J	1700 J
THALLIUM	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 U
ZINC	43	48	32
CYANIDE	N	N	N

ANALYSIS TYPE: SULFATE BY ANION SCAN

TITLE: UMTHUM TRUCKING

LAB: SILVER VALLEY

SAMPLE PREP:

REVIEW LEVEL: 2

MATRIX: WATER

METHOD: 3001WOO

CASE: 4740G

REVIEWER:

DATA FILE: P83

RESULT
394
0.10 U
21.8
334
20.2
258
155
37.3
37.9
180
258
50.0
181
135
142
374
69.0
68.0
12.0
268

ANALYSIS TYPE: CHLORIDE BY ANION SCAN

TITLE: UMTHUM TRUCKING

LAB: SILVER VALLEY

SAMPLE PREP:

ANALYST/ENTRY: PLC

REVIEWER:

DATA FILE: P82

MATRIX: WATER

UNITS: MG/L

CASE: 4740G

DATE: 08/03/89

SAMPLE NO.	RESULT
DC943001	33.0
DC943002F	0.10 U
DC943003	1.01
DC943004	40.0
DC943005	0.55
DC943006	64.8
DC943007	66.2
DC943008	2.10
DC943009	11.3
DC943010	190
DC943011	55.6
DC943012	14.0
DC943013	84.0
DC943014	61.6
DC943015	24.4
DC943016	112
DC943017	7.00
DC943017D	7.20
DC943018	1.30
DC943019	27.0

ANALYSIS TYPE: SULFIDE

TITLE: UMTHUM TRUCKING

LAB: SILVER VALLEY

SAMPLE PREP:

REVIEW LEVEL: 2

MATRIX: SEDIMENT

METHOD: 3761W01

CASE: 4740G

REVIEWER:

DATA FILE: P84

SAMPLE NO.	RESULT
DC943031	53.0
DC943032	21.2
DC943033	10.6
DC943034	10.6
DC943034D	21.2
DC943035	10.6
DC943036	10.6
DC943037	10.6
DC943038	21.2
DC943039	21.2
DC943040	21.2
DC943041	10.6
DC943042	10.6
DC943043	21.2
DC943044	10.6



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT 2

THRU:

Joseph Chandler, TATI

DATE:

August 3, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-QSH

These data were reviewed according to the "Laboratory Data -Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 4740G

LABORATORY: SILVER VALLEY

CONTRACT NO.: 68-W8-0074

METHOD NO .: 3001W00

SITE: UMTHUM TRUCKING

EPA ACTIVITY: DC943

REVIEWER: P. COX

MATRIX: WATER

SMO SAMPLE	NOS.	EPA SAMPLE NOS.	
MGE328	MGE338	DC943001	DC943011
MGE329	MGE339	DC943022F	DC943012
MGE330	MGE340	DC943003	DC943013
MGE331	MGE341	DC943004	DC943014
MGE332	MGE342	DC943005	DC943015
MGE333	MGE343	DC943006 '	DC943016
MGE334	MGE344	DC943007	DC943017
MGE335	MGE345	DC943008	DC943017D
MGE336	MGE346	DC943009	DC943018
MGE337	MGE347	DC943010	DC943019

GENERAL

Special Analytical Services (SAS)—case 4740G contained 20 water samples analyzed for anions chloride (Cl⁻) and sulfate (SO₄²-) by ion chromatography. Samples DC943003 (MGE330) and DC943005 (MGE332) had chloride and sulfate results reversed. Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

Technical holding times and required preservation were met on all samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Initial, continuing, and preparation blanks were analyzed with no chloride or sulfate being reported. Field blank DC943002F (MGE329) was analyzed with no anions reported.

SPIKES

· All analytes were within limit requirements for percent recovery.

PERFORMANCE EVALUTATION SAMPLE

No performance evaluation sample was submitted to the laboratory for analysis.



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT 4

THRU:

Joseph Chandler, TATL

DATE:

August 4, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-QSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 4740G

LABORATORY: SILVER VALLEY

CONTRACT NO.: 68-W8-0074

METHOD NO.: 3761W01

SITE: UMTHUM TRUCKING

EPA ACTIVITY: DC943

REVIEWER: P. COX

MATRIX: WATER

EPA SAMPLE NOS. SMO SAMPLE NOS.

MGE348	MGE358	DC943031	DC943040
MGE349	MGE359	DC943032	DC943041
MGE350	MGE360	DC943033	DC943042
MGE351	MGE361	DC943034	DC943043
MGE352	MGE362	DC943034D	DC943044
MGE353		DC943035	
MGE354		DC943036	
MGE355		DC943037	
MGE356		DC943038	0
MGE357		DC943039	

GENERAL

Special Analytical Services (SAS) case 4740G contained 16 soil/ash samples analyzed for sulfide by titrametric procedure. Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

No technical holding times or required preservation are specified for soil samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Continuing and preparation blanks were analyzed with sulfide being reported. No data was qualified by the blank rules.

SPIKES

All analytes were within limit requirements for percent recovery.

PERFORMANCE EVALUTATION SAMPLE

No performance evaluation sample was submitted to the laboratory for analysis.



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO: Debra Morey, Chemist, CLQA/LABO

FROM: Peggy Cox, TAT &

THRU: Joseph Chandler, TATL (Hat for IC.

DATE: August 15, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-2054-QSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 4740G LABORATORY: SILVER VALLEY

CONTRACT NO.: 68-W8-0074 METHOD NO.: 9001W71 SITE: UMTHUM TRUCKING EPA ACTIVITY: DC943

REVIEWER: P. COX MATRIX: SOIL

SMO SAMPLE NOS. EPA SAMPLE NOS. .

		· ·	
MGE348	MGE356	DC943031	DC943038
MGE349	MGE357	DC943032	DC943039
MGE350	MGE358	DC943033	DC943040
MGE351	MGE359	DC943034	DC943041
MGE352	MGE360	DC943034D	DC943042
MGE353	MGE361	DC943035	DC943043
MGE354	MGE362	DC943036	DC943044
MGE355		DC943037	

GENERAL

Special Analytical Services (SAS) request 4740G contained 15 soil samples analyzed for EP toxicity total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (Tl) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

No technical holding times or required preservation are specified for soil samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Antimony (Sb), barium (Ba), cobalt (Co), copper (Cu), and silver (Ag) were reported in the initial calibration blank and aluminum (Al), antimony (Sb), barium (Ba), calcium (Ca), copper (Cu), lead (Pb), magnesium (Mg), potassium (K), and silver (Ag) were reported in the continuing calibration blanks. Antimony (Sb) was reported in the preparation blank. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except sodium (Na) which was detected but not an element in the AB ICS solution. Sodium (Na) was reported at levels greater than the instrument detection limit (IDL). All data was qualified for sodium (Na) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements.

SPIKES

All analytes were within quality centrol limit requirements for percent recovery except lead (Pb), selenium (Se) and silver (Ag). All samples were qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirements. Several samples analyzed for arsenic (As), lead (Pb), selenium (Se), and thallium (Tl) had post digestion spike recoveries outside quality control limit requirements. No data was qualified by graphite furnace atonic absorption spectroscopy.

ICP SERIAL DILUTION

Aluminum (Al) and sodium (Na) were exceptions to the ICP rule for percent difference since the original concentration was less than 50 times the instrument detection limit (IDL). No data was qualified by the ICP serial dilution.

PERFORMANCE EVALUTATION SAMPLE

No performance evaluation sample was submitted to the laboratory for analysis.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 25 FUNSTON ROAD KANSAS CITY, KANSAS 66115

Date:	8/29/89
MEMORANDUI	<u>,</u> ,
SUBJECT:	Data Transmittal for Activity #: DC943, Site Description: Unthun Trucking
FROM:	Andrea Jirka Chief, Laboratory Branch, ENSV
TO:	P.Culver SPFD-WSTM
Attac	ched is the data transmittal for the above referenced
site. The	ese data have met all quality assurance requirements
unless in	dicated otherwise in the data package. This is a Modi-
fied Data	Transmittal; these data are modified and differ from
data prev	iously transmitted. If you have any questions or com-
ments, ple	ease contact Dee Simmons at 236-3881.
Attachment	, E
cc: Data Ann	File Melia, EBE/FIT
MODIFIED 1	DATA: Data were modified for the following reason(s):
1	ances to passes of CCS resided
0 +	- prevousey surmittee

DATA REPORTING / QUALIFICATION CODES

- U The material was analyzed for, but was not detected. The associated numerical value is the sample detection limit.
- J The associated numerical value is an estimated quantity (explanation attached).
- I The data are invalid (compound may or may not be present).
 Resampling and/or reanalysis is necessary for verification.
- N Sample not analyzed.

CODES FOR FLASH POINT DATA

- L The sample did not ignite or "flash". This is the highest temperature at which the sample was tested. It is possible that the material may be ignitable at higher temperatures.
- K The sample did ignite or "flash" at the lowest temperature tested. This is usually the ambient temperature at the time of the test. It is possible that the material may be ignitable at even lower temperatures.

TITLE: UMTHUM TRUCKING

MATRIX: WATER METHOD: 9001W71 UNITS: UG/L CASE: 12127

LAB: NANCO

DATE: 08/25/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE : P55

SAMPLES	DC943001	DC943002F	DC943003	DC943004
ALUMINUM	200 U	72 J	200 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC .	10 U	10 U	10 U	10 U
BARIUM	33 J	200 U	89 J	`50 J
BERYLLIUM	5.0 U	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	170000	5000 U	77000	170000
CHROMIUM	12 J	10 U	28 J	10 U
COBALT	50 บั	50 U	50 U	50 U
COPPER	25 U	25 U	13 J	25 U
IRON	410 U	100	160 U	170 U
LEAD	5.0 บ	0.40 J	5.0 U	5.0 U
MAGNESIUM	45000	5000 U	31000	46000
MANGANESE	210	15 U	4.0 J	52
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	40 U	8.0 J	40 U
POTASSIUM	5500	5000 U	1700 J	7500
SELENIUM	5.0 T	5.0 T	5.0 U	5.0 U
SILVER	10 U	10 U	10 U	. 10 U
SODIUM	16000	5000 T	14000	15000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 U	50 บ
ZINC	25 U	18 J	160	25 U
CYANIDE	N	n	N .	N

MATRIX: WATER UNITS: UG/L METHOD: 9001W71 ! CASE: 12127 CASE: 1212

SAMPLES	DC94300	DC943	006 DC94	3007	DC943	3008
ALUMINUM	200 U	200	ប 200	บ	200	U
ANTIMONY	60 U		Ŭ 60	-	60	Ŭ
ARSENIC	10 11	• •	Ŭ 10		10	Ŭ
BARIUM	110 J		J 63		98	Ĵ
BERYLLIUM	5.0 U		ับ 5.0		5.0	Ū
CADMIUM	5.0 U		Ŭ 5.0		5.0	U
CALCIUM	88000	150000	130000		77000	
CHROMIUM	10 U		J 10		10	U
COBALT	50 U		Ū 50		50	Ū -
COPPER	25 U		Ŭ 25		25	Ŭ
IRON	1800	520	340		1900	
LEAD	6.1 U		T 5.0		5.0	TT
MAGNESIUM	34000	47000	42000	_	33000	•
MANGANESE	10 J	210	250		26	
MERCURY	0.20 U		บ 0.20		0.20	U
NICKEL	40 U		J 40		40	ซื
POTASSIUM	1600 J	4000	J 3300		7300	•
SELENIUM	5.0 U	5.0	Ū 5.0		5.0	บ
SILVER	. 10 U	10	U 10		10	
SODIUM	19000	24000	28000		48000	J
THALLIUM	10 U	10	U 10		10	ប
VANADIUM	50 U	50	Ū 50		50	
ZINC	800	35	T 33		800	
CYANIDE	N	35	N	N	800	N
	N		74	7.4		74

MATRIX: WATER UNITS: UG/L CASE: 12127 PATE: 08/25/89 TITLE: UMTHUM TRUCKING LAB: NANCO

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55

SAMPLES	DC943009	DC943010	DC943011	DC943012
ALUMINUM	200 U	200 U	310 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM	`100 J	62 J	54 J	61 J
BERYLLIUM	5.0 U	5.0 U	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 บั	5.0 U	5.0 U
CALCIUM	90000	150000	110000	74000
CHROMIUM	10 U	9.0 J	28 Ј	10 U
COBALT	50 U	50 U	50 U	50 U :
COPPER	25 U	20 J	25 U	25 U
IRON	190 U	100 U	500 U	120 U
LEAD	5.0 T	5.3 U	5.0 T	5.0 U
MAGNESIUM	33000	56000	19000	29000
MANGANESE	12 J	49	71	11 J
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	22 J	40 U	40 U
POTASSIUM	1800 J	3200 J	11000	3000 J
SELENIUM	5.0 U	5.0 T	5.0 U	5.0 U
SILVER	10 U	· 10 U	10 U	. 10 U
SODIUM	16000	76000	35000	35000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 T	50 T	50 T	50 U
ZINC	510	1600	20 U	50 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING MATRIX: WATER UNITS: UG/L CASE: 12127
DATE: 08/25/89 METHOD: 9001W71 LAB: NANCO SAMPLE PREP: REVIEW LEVEL: 2

ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P55

SAMPLES	DC943013	DC943014	DC943015	DC943016
ALUMINUM	200 U	200 U	200 U	490 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	. 10 U	10 U	10 U	10 U
BARIUM	24 J	43 J	40 J	34 J
BERYLLIUM	5.0 U	2.0 J	5.0 U	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	53000	110000	91000	240000
CHROMIUM	10 U	10 U	10 U	16 J
COBALT	50 U	11 J	50 U	50 U -
COPPER	18 J	12 J	25 U	10 J
IRON	100 U	24000	140 U	610
LEAD	5.0 บ	8.6	5.0 T	5.1 U
MAGNESIUM	19000	29000	36000	3100 J
MANGANESE	52	150	5.0 J	43
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	40 U	71	19 J	14 J
POTASSIUM	5000 J	1700 J	7900	17000
SELENIUM	25 U	5.0 T	5.0 U	5.0 U
SILVER	10 U	10 U	10 U	10 U
SODIUM	180000	81000	12000	51000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	50 T	50 U	50 U	50 U
ZINC	540	1100	27 U	20 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING MATRIX: WATER UNITS: UG/L METHOD: 9001W71 LAB: NANCO F CASE: 12127

ANALYST/ENTRY: PLC REVIEWER: _______ DATA FILE : P55 SAMPLE PREP: DATE: 08/25/89

REVIEW LEVEL: 2

			•	
SAMPLES	DC943017	DC943017D	DC943018	DC943019
ALUMINUM	200 U	200 U	200 U	200 U
ANTIMONY	60 U	60 U	60 U	60 U
ARSENIC	10 U	10 U	10 U	10 U
BARIUM	79 J	81 J	48 J	120 J
BERYLLIUM '	5.0 U	5.0 U	5.0 บ	5.0 U
CADMIUM	5.0 U	5.0 U	5.0 U	5.0 U
CALCIUM	80000	78000	160000	85000
CHROMIUM	10 U	16 J	10 U	10 U
COBALT	50 U	50 U	50 U	50 U
COPPER	25 Ū	25 U	11 J	25 U
IRON	130 Ū	190 U	1000	1900
LEAD	5.0 T	5.0 T	5.0 T	5.0 U
MAGNESIUM	35000	35000	40000	33000
MANGANESE	5.0 J	5.0 J	28	21
MERCURY	0.20 U	0.20 U	0.20 U	0.20 U
NICKEL	9.0 J	16 J	13 J	40 U
POTASSIUM	2900 J	2400 J	1900 J	1600 J _
SELENIUM	5.0 U	5.0 T	5.0 T	5.0 T
SILVER	10 U	10 U	10 U	10 U
SODIUM	18000	17000	20000	12000
THALLIUM	10 U	10 U	10 U	10 U
VANADIUM	.50 บั	50 U	50 U	50 U
ZINC	20 U	28 U	20 U	1500
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING MATRIX: SEDIMENT UNITS: MG/KG METHOD: 9001W71 CASE: 12127 LAB: NANCO

DATE: 08/25/89

SAMPLE PREP: REVIEW LEVEL: 2 ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

6

SAMPLES	DC943031	DC943032	DC943033	DC943034
ALUMINUM	7300	6600	6600	6500
ANTIMONY	18 U	16 U	16 U	16 U
ARSENIC	5.9 J	5.0 J	4.9 J	5.0 J
BARIUM	53 J	49 J	36 J	52, J
BERYLLIUM	1.8	1.9	2.2	2.1
CADMIUM	0.60 J	0.53 J	0.81 J	1.3 U
CALCIUM	310000	320000	250000	300000
CHROMIUM	15	12	12	11
COBALT	6.6 J	4.5 J	4.0 J	3.9 J
COPPER	38 J	4.8 J	2.2 J	3.4 J
IRON	13000	15000	14000	13000
LEAD	12	10	7.4	6.1
MAGNESIUM	2400	2400	1000 J	1300 J
MANGANESE	520 J	590 J	450 J	500 J
MERCURY	0.15 U	0.13 U	0.13 U	0.13 U
NICKEL	13	15 .	13	14
POTASSIUM	1500 U	1800 ប	2200 U	1500 U
SELENIUM	0.69 J	0.75 J	0.65 J	0.62 J
SILVER	6.0	5.1	4.3	5.2
SODIUM	1500 U	1300 U	1300 U	1300 U
THALLIUM	0.30 J	0.37 J	0.24 J	0.23 J
VANADIUM	23 U	22 U	24 U	24 U
ZINC	96	56 U	110	75 U
CYANIDE	N	N	N	N

TITLE: UMTHUM TRUCKING UNITS: MG/KG MATRIX: SEDIMENT CASE: 12127 DATE: 08/25/89 LAB: NANCO METHOD: 9001W71

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

SAMPLES	DC943034	ID DC943035	DC943036	DC943037
ALUMINUM	7700	16000	4000	10000
ANTIMONY	18 J	35 J	35 J	13 J
ARSENIC	5.4 J	9.6 J	4.1 J	5.0 J
BARIUM	57	140	160	110
BERYLLIUM	2.4	1.9	2.9	1.4
CADMIUM	0.48 J	1.2 U	0.87 J	0.45 J
CALCIUM	340000	5300	5600	38000
CHROMIUM	12	21	8.7	16
COBALT	4.3 J	11 J	28	6.8 J
COPPER	5.3 J	6.0 U	7.3 U	5.7 U
IRON	1500 0	23000	37000	15000
LEAD	6.3	18	6.5	14
MAGNESIUM	1400	2800	950 J	2500 ·
MANGANESE	540 J	610 J	2200 J	790 J
MERCURY	0.12 U	0.12 U	0.14 U	0.11 U
NICKEL	14	22	64	16
POTASSIUM	1700 U	2100 U	1500 U	1900 U
SELENIUM	0.60 J	0.41 J	0.23 J	0.41 J
SILVER	5.3	2.4 U	2.9 U	2.3 U
SODIUM	1200 U	1200 U	1500 U	1100 U
THALLIUM	0.19 J	0.19 J	2.9 U	0.18 J
VANADIUM	28 U	39 U	21 U	28 U
ZINC	180	110	160	76 U
CYANIDE	N	N	N	N

MATRIX: SEDIMENT UNITS: MG/KG METHOD: 9001W71 CASE: 12127 TITLE: UMTHUM TRUCKING LAB: NANCO SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56 DATE: 08/25/89

SAMPLES	DC943	038	DC94	3039	DC94:	3040	DC943	3041
ALUMINUM	12000		8500		4300		3400	
ANTIMONY		J	25	J	12	บ	14	J
ARSENIC		J	5.9	J	3.6	J	3.2	J
BARIUM	100		86		67		68	
BERYLLIUM	1.1	J	1.6		0.82	J	0.80	J
CADMIUM	1.1	J	0.53	J	1.0	U	\ 1.0	Ŭ
CALCIUM	200000		22000		310000		390000	
CHROMIUM	18		16		6.8		6.8	
COBALT	8.5	J	7.7	J	10	U	1.8	J
COPPER	9.2	U	6.6	U	14	J	14	J
IRON	12000		17000		7900		6900	
LEAD	79		9.5		13		8.1	
MAGNESIUM	7800		7000		19000		9800	
MANGANESE	2000	J	730	J	430	J	420	
MERCURY	0.18	U	0.13	U	0.10	U	0.10	U
NICKEL	22		19		77		66	
POTASSIUM	4400	U	1300	U	1300		1000	U
SELENIUM		J	0.40	J	1.4	J	0.38	J
SILVER	5.5		2.6	U	2.9		4.0	
SODIUM	280	J	1300	U	1000	U	1000	
THALLIUM		J	2.6	U	0.18	J	2.0	U
VANADIUM	32	U	25	U	210		190	
ZINC	120		69	U	43	U	68	U
CYANIDE		N		N	•	N		N

TITLE: UMTHUM TRUCKING

MATRIX: SEDIMENT METHOD: 9001W71

UNITS: MG/KG

LAB: NANCO

CASE: 12127 DATE: 08/25/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P56

SAMPLES	DC943042	DC943043	DC943044
ALUMINUM	6700	4700	10000
ANTIMONY	18 U	16 U	15 J
ARSENIC	4.3 J	3.7 J	5.3 J
BARIUM	79	75	270
BERYLLIUM	1.2 J	1.1 J	1.4
CADMIUM	1.5 U	1.4 U	0.48 J
CALCIUM	160000	8000	3400
CHROMIUM	11	7.9	15
COBALT	3.2 J	6.0 J	11 J
COPPER	7.3 U	6.8 U	6.0 U
IRON	11000	12000	14000
LEAD	9.4	9.4	24
MAGNESIUM	6500	1500	1800
MANGANESE	420 J	420 J	2100 J
MERCURY	0.15 U	0.14 U	0.12 U
NICKEL	13	12	23
POTASSIUM	1500 U	1400 U	2300 U
SELENIUM	0.44 Ј	0.38 J	0.41 J
SILVER	2.9 U	2.7 U	2.4 U
SODIUM	1500 U	1400 U	1200 U
THALLIUM	2.9 U	2.7 U	0.22 J
VANADIUM	. 21 U	16 U	27 U
ZINC	63 U	130	110
CYANIDE	N	N	N



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

TO:

Debra Morey, Chemist, CLQA/LABO

MODIFIED DATA

FROM:

Peggy Cox, TAT Re

DATE:

August 25, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-OSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 12127

CONTRACT NO.: 68-W8-0060

SITE: UMTHUM TRUCKING

REVIEWER: P. COX

SMO SAMPLE NOS.

LABORATORY: NANCO METHOD NO.: 9001W71

EPA ACTIVITY: DC943

MATRIX: WATER

EPA SAMPLE NOS.

			
MGF169	MGE207	DC943001	DC
MGF170	MGE208	DC943002F	DC

MGF169	MGE207	DC943001	DC943011
MGF170	MGE208	DC943002F	DC943012
MGF171	MGE209	DC943003	DC943013
MGF172	MGE210	DC943004	DC943014
MGE201	MGE211	DC943005	DC943015
MGE202	MGE212	DC943006	DC943016
MGE203	MGE213	DC943007	DC943017
MGE204	MGE214	DC943008	DC943017D
MGE205	MGE215	DC943009	DC943018
MGE206	MGE216	DC943010	DC943019

GENERAL

Case 12127 contained 20 water samples analyzed for total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (T1) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

Technical holding times and required preservation were met on all samples, with the exception of mercury (Hg) preparation/analysis holding times which were exceeded by 6 days. All data was qualified by the holding time/preservation rules.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Arsenic (As), vanadium (V), and zinc (Zn) were reported in the continuing calibration blanks and aluminum (Al) and lead (Pb) in the preparation blank. Field blank DC943002F (MGF170) was analyzed with aluminum (Al), iron (Fe), lead (Pb), and zinc (Zn) reported. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except antimony (Sb) and potasium (K) which were detected but not an elements in the EPA ICS solution. Antimony was reported at levels less than the instrument detection limit (IDL) and potassium at levels greater than the instrument detection limit (IDL). All data was qualified for potassium (K) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements except chromium (Cr). All samples were qualified by the duplicate rules.

SPIKES

All analytes were within limit requirements for percent recovery except antimony—(Sb), selenium—(Se), and thallium (Tl). All data was qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirments. Various samples for arsenic (As), selenium (Se), and thallium (T1) were qualified due to post digestion spike recoveries being outside quality control limits.

ICP SERIAL DILUTION

Aluminum (Al), iron (Fe), potassium (K), and zinc (Zn) were exceptions to the ICP rule for percent difference since the original sample concentration was less than 50 times the instument detection limit (IDL). No data was qualified by the ICP serial dilution rules.

PERFORMANCE EVALUTATION SAMPLE

No performance evaluation sample was submitted to the laboratory for analysis.



ecology and environment, inc.

CLOVERLEAF BUILDING 3, 6405 METCALF, OVERLAND PARK, KANSAS 66202, TEL. 913/432-9961

International Specialists in the Environment

MEMORANDUM

MODIFIED DATA

TO:

Debra Morey, Chemist, CLQA/LABO

FROM:

Peggy Cox, TAT %

DATE:

August 25, 1989

SUBJECT: Review of data for UMTHUM TRUCKING

TDD# T07-8904-013 PAN# T07-Z054-QSH

These data were reviewed according to the "Laboratory Data Validation Functional Guidelines for Evaluation of Inorganic Analyses," July 1, 1988 revision.

The following comments and attached data sheets are a result of Ecology & Environment Inc.'s review of the above mentioned data from the contract laboratory.

CASE NO.: 12127 CONTRACT NO.: 68-W8-0060 SITE: UMTHUM TRUCKING REVIEWER: P. COX

LABORATORY: NANCO METHOD NO.: 9001W71 EPA ACTIVITY: DC943 MATRIX: WATER/ASH/SOIL

SMO SAMPLE NOS.

EPA SAMPLE NOS.

MGE217	MGE225	DC943900P	DC943037
MGE218	MGE226	DC943031	DC943038
MGE219	MGE227	DC943032	DC943039
MGE220	MGE228	DC943033	DC943040
MGE221	MGE229	DC943034	DC943041
MGE222	MGE230	DC943034D	DC943042
MGE223	MGE231	DC943035	DC943043
MGE224	MGE232	DC943036	DC943044

GENERAL

Case 12127 contained 16 water/ash/soil samples analyzed for total metals at the low level concentration. Arsenic (As), lead (Pb), selenium (Se), and thallium (Tl) were analyzed by graphite furnace atomic absorption (GFAA) spectroscopy and mercury (Hg) by cold vapor (CV). Data review was performed at level 2.

HOLDING TIMES and PRESERVATION

No technical holding times or required preservation are specified for soil samples.

INITIAL and CONTINUING CALIBRATION

Initial and continuing calibrations were within quality control limit requirements on all parameters.

BLANKS

Arsenic (As) was reported in the water matrix initial calibration blank and aluminum (Al), iron (Fe), potassium (K), vanadium (V), and zinc (Zn) in the continuing calibration blanks. Chromium (Cr) was reported in the water matrix preparation blank. Associated analyte data was qualified by the blank rules.

ICP INTERFERENCE CHECK

All analytes contained in the ICP interference check sample were within quality control limit requirements except antimony (Sb) and potasium (K) which were detected but not an elements in the EPA ICS solution. Antimony was reported at levels greater than the instrument detection limit (IDL) and potassium at levels less than the instrument detection limit (IDL). All data was qualified for antimony (Sb) by the ICP interference check.

LABORATORY CONTROL SAMPLE

All laboratory control samples analyzed met quality control limit requirements.

DUPLICATES

All analytes were within quality control limit requirements.

SPIKES

All analytes were within limit requirements for percent recovery except antimony—(Sb), arsenic—(As), copper (Cu), manganese (Mn), selenium (Se), and thallium (Tl) in the soil matrix sample and silver (Ag) in the water matrix sample. Associated sample data was qualified by the spike recovery rules.

GRAPHITE FURNACE ATOMIC ABSORPTION (GFAA)

All parameters requiring GFAA analysis met contractual requirments. Various samples for selenium (Se) and thallium (Tl) were qualified due to post digestion spike recoveries being outside quality control limits.

ICP SERIAL DILUTION

Barium (Ba), beryllium (Be), magnesium (Mg), and vanadium (V) in the soil matrix sample and cadmium (Cd) and nickel (Ni) in the water matrix sample were exceptions to the ICP rule for percent difference since the original sample concentration was less than 50 times the instument detection limit (IDL). No data was qualified by the ICP serial dilution rules.

PERFORMANCE EVALUTATION SAMPLE

Performance evaluation sample DC943900P (MGE217) was analyzed with all anlytes present in the audit being identified. Calcium (Ca) and sodium (Na) were also reported. No data was qualified by the performance evaluation sample.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 25 FUNSTON ROAD KANSAS CITY, KANSAS 66115

Date:	10/12/89
SUBJECT:	Data Transmittal for Activity #: DC943, Site Description: Umthun Trucking
FROM:	Andrea Jirka X Chief, Laboratory Branch, ENSV
TO:	P. Culver SPFD-WSTM
Attac	ched is the data transmittal for the above referenced
site. The	ese data have met all quality assurance requirements
unless ind	dicated otherwise in the data package. This is a Modi-
fied Data	Transmittal; these data are modified and differ from
data previ	iously transmitted. If you have any questions or com-
ments, ple	ease contact Dee Simmons at 236-3881.
Attachment	E
cc: Data Annl	File Volva, EBE /FIT
MODIFIED I	DATA: Data were modified for the following reason(s):
respon	se to results of CCS resulted in
chano	es to premously submitted Inta
·) 1

DATA REPORTING / QUALIFICATION CODES

- U The material was analyzed for, but was not detected. The associated numerical value is the sample detection limit.
- J The associated numerical value is an estimated quantity
 (explanation attached).
- I The data are invalid (compound may or may not be present).
 Resampling and/or reanalysis is necessary for verification.
- N Sample not analyzed.

CODES FOR FLASH POINT DATA

- L The sample did not ignite or "flash". This is the highest temperature at which the sample was tested. It is possible that the material may be ignitable at higher temperatures.
- K The sample did ignite or "flash" at the lowest temperature tested. This is usually the ambient temperature at the time of the test. It is possible that the material may be ignitable at even lower temperatures.

TITLE: UMTHUM TRUCKING MATRIX: WATER UNITS: UG/L - METHOD: 9001W71 CASE: 4740G DATE: 10/03/89 LAB: SILVER VALLEY

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE : PO7

SAMPLES	DC94303	1 DC943	032	DC94	3033	DC943	3034
ALUMINUM	210	. 200	U	200	U	200	U
ANTIMONY	60 U	60	U	60	U	. 60	U
ARSENIC	10 U	3.0	J	2.5	J	10	U
BARIUM	130 J	130	J	43	J	120	J
BERYLLIUM	5.0 U	5.0	U	5.0	U	5.0	U
CADMIUM	5.0 U	5.0	U	5.0	U	5.0	U
CALCIUM	350000	2100	J 44	0000		460000	
CHROMIUM	10 U	10	U	10	U	10	U
COBALT	50 U	50	U	50	U	50	U
COPPER	25 U	25	U	25	U	25	U
IRON	11 J	100	U	27	J	100	U
LEAD	5.0 U	5.0	U	5.0	บ	5.0	U
MAGNESIUM	4600 J	15000		7500		7300	
MANGANESE	15 U	1200		940		1500	
MERCURY	0.20 U	0.20	U	0.20	U	0.20	U
NICKEL	40 U	40	U	40	U	40	U
POTASSIUM	4600 J	25000	3	6000		23000	
SELENIUM	50 U		U	50	U	50	U
SILVER	10 U	10	Ų	10	U	10	U
SODIUM	900 J	2600		3300	J	2600	J
THALLIUM	10 U	1.6	J	1.1	J	0.90	J
VANADIUM	8.0 J	8.9	J	10	J	12	J
ZINC	20 U	20	U	8.8	J	6.3	J
CYANIDE	N		N		N		N

UNITS: UG/L TITLE: UMTHUM TRUCKING MATRIX: WATER METHOD: 9001W71 CASE: 4740G LAB: SILVER VALLEY

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE: P07 DATE: 10/03/89

SAMPLES	DC943	3034D	DC943	3035	DC943	3036	DC943	3037
ALUMINUM	200	U	200	U	200	U	120	J
ANTIMONY	60	U	60	U	60	U	60	U
ARSENIC	4.4	J	10	U	10	U	100	U
BARIUM	160	J	240		440		760	
BERYLLIUM	5.0	U	5.0	U	5.0	U	5.0	U
CADMIUM	5.0	U	5.0	U	5.0	υ΄	5.0	Ŭ
CALCIUM	440000		53000		150000		260000	
CHROMIUM	10	U	10	U	10	U	10	U
COBALT	50	U	50	U	50	U	50	U
COPPER	25	U	25	U	25	U	25	U
IRON	100	U	18	J	120		100	U
LEAD		U	5.0	U		U	5.0	Ŭ
MAGNESIUM	7100		4300	J	9000		25000	
MANGANESE	1500		130		8000		4300	
MERCURY	0.20	U	0.20	U	0.20	U	0.20	
NICKEL	• •	U	40	U	40	Ŭ	40	U
POTASSIUM	23000		10000		5000	U	12000	
SELENIUM	50	Ŭ	5.0	Ŭ	5.0	U	50	U
SILVER	10	U	10	U,	10	U	10	U
SODIUM		J	320		580	J	790	J
THALLIUM	0.90	J	10	U	1.0	J	1.2	J
VANADIUM	12	J	50	U	50	U	4.1	J
ZINC	6.6	J	20	U	23		30	
CYANIDE		N		N		N		N

TITLE: UMTHUM TRUCKING MATRIX: WATER UNITS: UG/L LAB: SILVER VALLEY METHOD: 9001W71 CASE: 4740G SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATE: 10/03/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE : P07

SAMPLES	DC943	038	DC943	3039	DC943	3040	DC943	3041	
ALUMINUM	88	J	200	U	200	U	200	U	
ANTIMONY	60	U	60	U	60	U	60	U	
ARSENIC	10	U	10	U	10	U	10	U	
BARIUM	260		550		220		670		
BERYLLIUM	5.0	U	0.90	J	5.0	U	5.0	U	•
CADMIUM	5.0	U	3.4	J	5.0	U	5.0	U	
CALCIUM	440000		480000		670000		580000		
CHROMIUM	10	U	10	U	10	U	10	U	
COBALT	50	U	50	U	50	U	50	U	
COPPER	25	U	25	U	25	U	25	U	
IRON	14	J	29	J	100	U	100	U	
LEAD	5.0	U	5.0	U	50	U	50	U	
MAGNESIUM	53000		120000		140	J	5000	U	
MANGANESE	13000		5900		2.4	J	15	U	
MERCURY	0.20	U	0.20	U	0.20	U	0.40		
NICKEL	51		44		40	U	40	U	
POTASSIUM	33000		5000	U	8700		3300	J	
SELENIUM	50	U	5.0	U	50	U	50	U	
SILVER	10	U	10	U,	10	U	10	U	
SODIUM		J	690	J'	1700	J	790	J	
THALLIUM	3.9	J	1.0	J	1.4	J	10	U	
VANADIUM		J	50	Ū	14	J	4.4	J	
ZINC		Ū	7.4	J	.20	U	20	U	
CYANIDE		N		N		N		N	

TITLE: UMTHUM TRUCKING

MATRIX: WATER

LAB: SILVER VALLEY

METHOD: 9001W71

UNITS: UG/L CASE: 4740G DATE: 10/03/89

SAMPLE PREP: ANALYST/ENTRY: PLC REVIEWER: DATA FILE : P07

			•
SAMPLES	DC943042	DC943043	DC943044
ALUMINUM	200 U	200 U	200 U
ANTIMONY	60 U	27 J	60 U
ARSENIC	2.3 J	2.8 J	10 U
BARIUM	810	760	460
BERYLLIUM	5.0 U	5.0 U	5.0 U
CADMIUM .	5.0 U	5.0 U	5.0 U
CALCIUM	380000	210000	35000
CHROMIUM	10 U	10 U	10 U
COBALT	29 J	62	50 U
COPPER	25 U	25 U	25 U
IRON	37 J	420	110
LEAD	5.0 U	5.0 U	5.0 U
MAGNESIUM	18000	23000	3500 J
MANGANESE	6600	13000	1400
MERCURY	0.20 U	0.20 U	0.20 U
NICKEL	54	47	40 U
POTASSIUM	5000 Ŭ	5000 U	8700
SELENIUM	50 U	5.0 U	5.0 U
SILVER	10 U	10 U ,	10 U
SODIUM	1200 J	1200 J,	1700 J
THALLIUM	10 U	10 U	10 U
VANADIUM	50 U	50 U	50 U
ZINC	43	48	32
CYANIDE	N	N	N